NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.
SAMPLING DATE: 10-20-01
ADDRESS: 345 Chambers St., NY,NY 10282

T01102 1A

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
1	North Entrance of H.S-East	1559	2400	3	3	1437	0	0	<16.67	<0.0045
2	North Entrance of H.S-West	1601	2401	3	3	1440	0	0	<16.67	<0.0045

RECEIVED
KAM CONSULTANTS
2001 OCT 21 AM 6:27

TECHNICIAN: R. Dymkowska
ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX results to DDC	RECEIVED AT LAB BY: SAMPLE CONDITION UPON RECEIPT: DATE/TIME:

ANALYST: [signature]
DATE RECEVED: 10/21
DATE OF ANALYSIS 10/21

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

CITY_21MC100_009251584

NYC-WTC_000209011