



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 10-22-01
ADDRESS: 345 Chambers St., NY, NY 10282

RECEIVED
KAM CONSULTANTS

TOK 022E

2001 OCT 22 PM 5:11

FIELD DATA							LAB ANALYSIS				
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (struc/mm ²)	Structure Concentration (struc/cc)	
							0.5-5.0 (μ)	>5.0 (μ)			
1	North Entrance of H.S.-East	0759	1659	3	3	1440	0	0	2	6.67	<0.0045
2	North Entrance of H.S.-West	0801	1601	3	3	1440	↓	↓	↓		↓

TECHNICIAN: R. Dymkowska

ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX Results to DDC.	RECEIVED AT LAB BY: <i>AS</i>
		SAMPLE CONDITION UPON RECEIPT:
		DATE/TIME:

ANALYST:

ALEXS Dymkowska

DATE RECEIVED:

10/22/01

DATE OF ANALYSIS

10/22/01

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)

Sample Volume may be below recommended limit of the method.

FAX RESULTS TO (212) 941-5356