



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 11-27-01
ADDRESS: 345 Chambers St., NY, NY 10282

7011127F

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (struc/mm ²)	Structure Concentration (struc/cc)
							0.5-5.0 (μ)	>5.0 (μ)		
1	Pier-25 North Entrance of school East	00:01	8:00	3	3	1437	0	0	<16.67	<0.0045
2	- " - 11 - West	00:02	8:01	3	3	1437	0	0	<16.67	<0.0045

RECEIVED
KAM CONSULTANTS
2001 NOV 27 AM 9:04

TECHNICIAN: R. Dymkowska

ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX results to DDC.	RECEIVED AT LAB BY:
		SAMPLE CONDITION UPON RECEIPT:
		DATE/TIME:

ANALYST:

[Signature]

DATE RECEIVED:

11/27/01

DATE OF ANALYSIS

11/27

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)

Sample Volume may be below recommended limit of the method.

FAX RESULTS TO (212) 941-5356

CITY_21MC100_009251677