



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

ANALYSIS REPORT
ASBESTOS IN AIR
Transmission Electron Microscopy

CLIENT: Department of Design and Construction - 30-30 Thomson Avenue, Long Island City, NY 11101
PROJECT ADDRESS: Stuyvesant H.S., 345 Chambers St., NY, NY 10282 Pier #25

Lab ID#	Client Sample ID#	Sample Location	Volume (liters)	Grid Openings Examined	Filter Area (mm ²)	Analytical Sensitivity (struct/cc air)	Asbestos Type(s)	Asbestos Structures (microns)		Detected Total	Structure Density (struct/mm ²) Total	Structure Concentration (struct/cc) Total
								0.5-5.0	>5.0			
T011205F-01	1	North Entrance of School - East	1437	6	385	0.0050	ND	0	0	0	<18.51	<0.0050
T011205F-02	2	North Entrance of School - West	1437	6	385	0.0050	ND	0	0	0	<18.51	<0.0050

Area Analyzed: 0.0600 mm²

Grid Opening Area: 0.010 mm²

Date Collected: 12/05/01(00:00-08:00)

Analyst: _____

David Chen

Date Received: 12/05/01

Date Analyzed: 12/05/01

Date of Report: 12/12/01

Lab Manager: _____

David Chen

Analysis performed according to AHERA Method (EPA 40 CFR Part 763 - Appendix A) Samples will be stored for ninety (90) days and then returned to the client upon request.
Sample volume is below recommended limit of the method

AHHA #: 100269

NIST-NVLAP #: 102047

NYS-DOH ELAP#: 11273

CITY_21MC100_010404834