



KAM CONSULTANTS
 35-40 36th Street
 Long Island City
 New York, 11106
 Tel: (718) 729-1997
 Fax: (718) 729-1876

ANALYSIS REPORT

ASBESTOS IN AIR Transmission Electron Microscopy

CLIENT: Department of Design and Construction - 30-30 Thomson Avenue, Long Island City, NY 11101
PROJECT ADDRESS: Stuyvesant H.S., 345 Chambers St., NY, NY 10282 **Pier #25**

Lab ID#	Client Sample ID#	Sample Location	Volume (liters)	Grid Openings Examined	Filter Area (mm ²)	Analytical Sensitivity (struct/cc air)	Asbestos Type(s)	Asbestos Structures Detected (microns)			Structure Density (struct/mm ²) Total	Structure Concentration (struct/cc) Total
								0.5-5.0	>5.0	Total		
T011209A-01	1	Outside North Entrance of School - East Side	1431	6	385	0.0045	ND	0	0	0	< 16.67	< 0.0045
T011209A-02	2	Outside North Entrance of School - West Side	1428	6	385	0.0045	ND	0	0	0	< 16.67	< 0.0045

Area Analyzed: 0.0600 mm²
 Grid Opening Area: 0.010 mm²
 Date Collected: 12/08/01(16:00-00:00)

Date Received: 12/09/01
 Date Analyzed: 12/09/01
 Date of Report: 12/13/01

Analyst: _____

Alex Berengolts

Lab Manager: _____

David Chen

Analysis performed according to AHERA Method (EPA 40 CFR Part 763 - Appendix A) Samples will be stored for ninety (90) days and then returned to the client upon request.
 Sample volume is below recommended limit of the method

AIHA #: 100269

NIST-NVLAP #: 102047

NYS-DOH ELAP#: 11273

CITY_21MC100_010404845