



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC

PROJECT: Stuyvesant H.S.

SAMPLING DATE: 12/1/01

ADDRESS: 345 Chambers St., NY, NY 10282

T011202A

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (struc/mm ²)	Structure Concentration (struc/cc)
							0.5-5.0 (μ)	>5.0 (μ)		
1	PIER #25 OUTSIDE NORTH ENTRANCE OF SCHOOL - EAST SIDE	16.01	23.58	3	3	1431	0	0	1/6.87	10.0045
2	↓ WEST SIDE	16.02	23.59	3	3	1431	1	1	1	↓

RECEIVED
KAM CONSULTANTS
1001 DEC -2 AM 9:10

TECHNICIAN: A. MARSHOSSIAN

ROTAMETER: KAM101

CHAIN OF CUSTODY	PLEASE, FAX RESULTS TO	RECEIVED AT LAB BY: <i>MS</i>
	NYC DDC	SAMPLE CONDITION UPON RECEIPT:
		DATE/TIME:

ANALYST: ALEXS BARENOVA

DATE RECEIVED: 12-02

DATE OF ANALYSIS 12-02

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)

Sample Volume may be below recommended limit of the method

FAX RESULTS TO (212) 941-5356