NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTOL FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.
SAMPLING DATE: 12/5/01
ADDRESS: 345 Chambers St., NY,NY 10282

T01120613

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
	PIER #25									
1	OUTSIDE NORTH ENTRANCE OF SCHOOL - EAST SIDE	16.00	23.57	3	3	1431	0	0	<16.67	<0.0047
2	↓ - WEST SIDE	16.01	23.58	3	3	1431	0	0	<16.67	<0.0047

RECEIVED KAM CONSULTANTS DEC -6 AM 9:12

TECHNICIAN: A. MARTIROSSIAN
ROTAMETER: KAM101

CHAIN OF CUSTODY	PLEASE, FAX RESULTS TO NYC DDC	RECEIVED AT LAB BY: SAMPLE CONDITION UPON RECEIPT: DATE/TIME:

ANALYST: [signature]
DATE RECEVED: 12/6
DATE OF ANALYSIS 12/6/01

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

CITY_21MC100_009251842

NYC-WTC_000209034