



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 12-6-01
ADDRESS: 345 Chambers St., NY, NY 10282

Toll 1206/4

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (struc/mm ²)	Structure Concentration (struc/cc)
							0.5-5.0 (μ)	>5.0 (μ)		
1	Pier - 25 North Entrance of school - East	00:01	7:31	3	3	1350	0	0	<16.67	<0.0045
2	- " - " - West	00:02	7:32	3	3	1350	0	0	<16.67	<0.0045

RECEIVED
KAM CONSULTANTS
DEC - 6 AM 9:09

TECHNICIAN: Renata Dymkowska

ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX results to DDC.	RECEIVED AT LAB BY: [Signature]
		SAMPLE CONDITION UPON RECEIPT: good
		DATE/TIME: 12/6

ANALYST: [Signature]

DATE RECEIVED: 12/6

DATE OF ANALYSIS 12/6

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (ASHERA)
Sample Volume may be below recommended limit of the method.

FAX RESULTS TO (212) 941-5356