



35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTO. FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 1-26-02
ADDRESS: 345 Chambers St., NY, NY 10282

T010127A

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (struc/mm ²)	Structure Concentration (struc/cc)
							0.5-5.0 (μ)	>5.0 (μ)		
	PIER 25									
1	North Entrance of school - East	7:01	17:01	3	3	1800	0	0	4220	100043
2	-11 - " - West	7:02	17:02	3	3	1800	1	1	4220	100043

TECHNICIAN: Renata Dymkowska

ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX results to DDC.	RECEIVED AT LAB BY:
		SAMPLE CONDITION UPON RECEIPT: DATE/TIME:

ANALYST: Aleks Bawejny

DATE RECEIVED: 1-27-02

DATE OF ANALYSIS: 1-28-02

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)

Sample Volume may be below recommended limit of the method

FAX RESULTS TO (212) 941-5356