NYC 9/11 Public Portal Document

35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTOL FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 1/29/02
ADDRESS: 345 Chambers St., NY, NY 10282

T020130 A.

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
1	North Piez #2.5 EXIT OF Stuyvesant H.S.	0700	1700	3	3	1800	0	0	<20.00	<0.0043
2	North west site	0701	1701	3	3	1800	0	0	<20.00	<0.0043

TECHNICIAN: D. SALIS
ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX RESULTS TO N.Y.C D.D.C	RECEIVED AT LAB BY: SAMPLE CONDITION UPON RECEIPT: DATE/TIME:

ANALYST: [signature] DATE RECEVED: 1/30/02 DATE OF ANALYSIS 1/30/02

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

CITY_21MC100_009252008

NYC-WTC_000209053