



35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 2-25-02
ADDRESS: 345 Chambers St., NY, NY 10282

721 906 717-55

T020226F

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (struc/mm ³)	Structure Concentration (struc/cc)
							0.5-5.0 (μ)	>5.0 (μ)		
	PIER 25									
1	North Entrance of school - East	7:00	7:01	3	3	1803	0	0	< 20.0	< 0.0043
2	- " - " - West	7:01	7:02	3	3	1803	0	0	< 20.0	< 0.0043

TECHNICIAN Renata Dymkowska

ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX results to DDC.	RECEIVED AT LAB BY: AR
		SAMPLE CONDITION UPON RECEIPT: SD
		DATE/TIME:

ANALYST ALEXIS BARNER DATE RECEIVED 2-26 DATE OF ANALYSIS 2-28-02

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method
FAX RESULTS TO (212) 941-5356

CITY_21MC100_009252032