



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

ANALYSIS REPORT
ASBESTOS IN AIR
Transmission Electron Microscopy

CLIENT: Department of Design and Construction - 30-30 Thomson Avenue, Long Island City, NY 11101
PROJECT ADDRESS: Stuyvesant H.S., 345 Chambers St., NY, NY 10282 **Pier #25**

Lab ID#	Client Sample ID#	Sample Location	Volume (liters)	Grid Openings Examined	Filter Area (mm ²)	Analytical Sensitivity (struct/cc air)	Asbestos Type(s)	Asbestos Structures (microns)		Detected Total	Structure Density (struct/mm ²) Total	Structure Concentration (struct/cc) Total
								0.5-5.0	>5.0			
T020220Z-01	1	North Entrance of School - East	1890	6	385	0.0041	ND	0	0	0	<20.00	<0.0041
T020220Z-02	2	North Entrance of School - West	1890	6	385	0.0041	ND	0	0	0	<20.00	<0.0041

Area Analyzed: 0.0600 mm²
Grid Opening Area: 0.010 mm²
Date Collected: 02/20/02(06:30-17:00)

Date Received: 02/20/02
Date Analyzed: 02/21/02
Date of Report: 02/22/02

Analyst: _____

David Chen

Lab Manager: _____

David Chen

Analysis performed according to AHERA Method (EPA 40 CFR Part 763 - Appendix A). Samples will be stored for ninety (90) days and then returned to the client upon request.
Sample volume is below recommended limit of the method
AIHA #: 100269

NIST-NVLAP #: 102047

NYS-DOH ELAP#: 11273