

PLM QUALITATIVE WIPE ANALYSIS

CLIENT: NYU **PROJECT#:** NY-038-02 **DATE:** 2/25/02
LOCATION: 100 Trinity Street, Basement

Sample ID#	Location of Sample	PLM Analysis
B-16	Play Room-air vent duct	ND
B-17	"B" Stairs-top of electric box	ND
B-18	Room B14-top of drop ceiling	ND
B-19	Boiler Room-top of engine	ND
B-20	Room B11-air vent duct	ND
01-81	Electrical room	ND
01-82	Boiler room	ND
01-83	Stairs "D"	ND
01-84	By passenger elevator	ND
01-85	By stairs "B"	ND
01-86	By entrance to Gym room	ND
01-87	In Gym room -on top of table	ND
01-88	Gym room-corner floor	ND
01-89	North-South corner-floor	ND
01-90	South-West corner-floor	ND
01-91	Gym room-top of lights	ND
01-92	Locker room	ND
01-93	In front of paint room	ND
01-94	Electrical room	ND
01-95	Electrical room	ND

PLM= Polarized Light Microscopy

ND= None Detected

PLM QUALITATIVE WIPE ANALYSIS

CLIENT: NYU **PROJECT#:** NY-038-02 **DATE:** 2/25/02
LOCATION: 100 Trinity Street, 1st Floor

Sample ID#	Location of Sample	PLM Analysis
01-13	Stairs "B"	ND
01-14	Room 102A-around air vent duct	ND
01-15	Lobby-air vent duct	ND
01-61	Entrance to Lobby	ND
01-62	In front of lobby on carpet	ND
01-63	In front of Lobby on carpet	ND
01-64	Room 105 in front of door	ND
01-65	Men's room on the floor	ND
01-66	Room 104-window ledge	ND
01-67	Room 104-window edges	ND
01-68	Gym room-window edges	ND
01-69	Gym room-window edges	ND
01-70	Storage room-window	ND
01-71	Storage room-on the floor (VAT)	ND
01-72	Storage room-behind shelves	ND
01-73	Storage room-book shelves	ND
01-74	Stairs "A"	ND
01-75	Stairs "A"	ND
01-76	By entrance to stairs "A"	ND
01-77	Middle of Lobby	ND
01-78	By stairs "C"	ND
01-79	Auditorium by exit	ND
01-80	Balcony in auditorium	ND

PLM= Polarized Light Microscopy

ND= None Detected

PLM QUALITATIVE WIPE ANALYSIS

CLIENT: NYU **PROJECT#:** NY-038-02
LOCATION: 100 Trinity Street, 2nd Floor

DATE: 2/25/02

Sample ID#	Location of Sample	PLM Analysis
02-10	Room 204-top of drop ceiling	ND
02-11	Room 205-air vent duct	ND
02-12	Room 205-top of chair	ND
02-41	Stairs "B"	ND
02-42	Stairs "B"	ND
02-43	By passenger elevator	ND
02-44	Room 203 AC-supply	ND
02-45	Room 203- AC-return	ND
02-46	Room 203-book shelves	ND
02-47	Room 203-computer desk	ND
02-48	Room 204-top of ceiling	ND
02-47	Room 204-AC-supply	ND
02-50	Room 204-AC-return	ND
02-51	Room 205-AC-supply	ND
02-52	Room 205-AC-return	ND
02-53	Room 205-top of ceiling	ND
02-54	Room 205-carpet on wall	ND
02-55	Room 209-balcony on top of seats	ND
02-56	Room 209-balcony on top of seats	ND
02-57	Stairs "A"	ND
02-58	Stairs "A"	ND
02-59	Room 207-AC-supply	ND
02-60	Room 207 top of ceiling	ND

PLM= Polarized Light Microscopy

ND= None Detected

PLM QUALITATIVE WIPE ANALYSIS

CLIENT: NYU **PROJECT#:** NY-038-02
LOCATION: 100 Trinity Street, 3rd Floor

DATE: 2/25/02

Sample ID#	Location of Sample	PLM Analysis
03-07	Room 306-air vent duct	ND
03-08	Room 308-top of shelf	ND
03-09	Room 305-desk top-middle of room	ND
03-21	Room 304-air conditioning unit	ND
03-22	Room 304-book shelves	ND
03-23	Room 304-carpet on wall	ND
03-24	Room 305-air conditioning unit	ND
03-25	Room 305-book shelves	ND
03-26	Room 306-on top of lights	ND
03-27	Room 306-behind shelves	ND
03-28	Room 307-air conditioning unit	ND
03-29	Room 307-edges of floor	ND
03-30	Room 308-on top of shelves	ND
03-31	Room AC SP #305	ND
03-32	Room AC RT #305	ND
03-33	Room 305-floor	ND
03-34	Room 304-floor	ND
03-35	Room 306-AC-supply	ND
03-36	Room 306-AC-return	ND
03-37	Room 307 AC return	ND
03-38	Room 307-AC supply	ND
03-39	Room 308-AC supply	ND
03-40	Stairs "B"	ND

PLM= Polarized Light Microscopy

ND= None Detected

PLM QUALITATIVE WIPE ANALYSIS

CLIENT: NYU **PROJECT#:** NY-038-02 **DATE:** 2/25/02
LOCATION: 100 Trinity Street, 4th Floor

Sample ID#	Location of Sample	PLM Analysis
4-04	Room 405-air vent duct	ND
4-05	Room 406-top of shelf	ND
4-06	Room 409-on top of drop ceiling	ND
4-11	Room 405-air conditioning unit	ND
4-12	Room 405-computer desk	ND
4-13	Room 405-book shelves	ND
4-14	Room 406-computer table	ND
4-15	Room 404-behind refrigerator	ND
4-16	Room 404-air conditioning unit	ND
4-17	Room 409-on top of ceiling	ND
4-18	Room 409-behind lights	ND
4-19	Room 410-behind ceiling	ND
4-20	Room 410- computer desk	ND

PLM= Polarized Light Microscopy

ND= None Detected

PLM QUALITATIVE WIPE ANALYSIS

CLIENT: NYU **PROJECT#:** NY-038-02 **DATE:** 2/25/02
LOCATION: 100 Trinity Street, 5th Floor

Sample ID#	Location of Sample	PLM Analysis
5-01	Room 505-air vent duct	ND
5-02	Room 509-on top of drop ceiling	ND
5-03	Room 504-desk top-middle of room	ND
5-01	Room 508-air conditioning unit	ND
5-02	Room 508-ceiling tiles	ND
5-03	Room 508-crpet-floor	ND
5-04	Room 504-air conditioning unit	ND
5-05	Room 504-book shelves	ND
5-06	Room 504-computer table	ND
5-07	Room 503-carpet-floor	ND
5-08	Room 503-carpet-floor	ND
5-09	Room 503-computer desk	ND
5-10	Room 504-behind ceiling tiles	ND

PLM= Polarized Light Microscopy

ND= None Detected

PLM QUALITATIVE WIPE ANALYSIS

CLIENT: NYU **PROJECT#:** NY-038-02 **DATE:** 2/25/02
LOCATION: 100 Trinity Street, 6th Floor

Sample ID#	Location of Sample	PLM Analysis
6-35	Room 606-air supply	ND
6-36	Room 606-baseboard	ND
6-605-82	Classroom 605-AC supply	ND
6-605-83	Classroom 605-top of ceiling tile	ND
6-605-84	Room 603-chair	ND
6-A-85	Staircase A, floor-step	ND
6-B-86	Staircase B-floor-vestibule	ND
6-606-87	Room 606-inside AC-duct	ND
6-606-88	Room 606-top of AC-duct	ND
6-ELV-89	Elevator Lobby-by elevator #1	ND
6-ELC-90	Electrical closet-floor	ND
6-607-91	Room 607-inside AC-inside duct	ND
6-607-92	Room 607-outside AC-outside duct	ND

PLM= Polarized Light Microscopy

ND= None Detected

PLM QUALITATIVE WIPE ANALYSIS

CLIENT: NYU **PROJECT#:** NY-038-02
LOCATION: 100 Trinity Street, 7th Floor

DATE: 2/25/02

Sample ID#	Location of Sample	PLM Analysis
7-32	Room 703-air supply	ND
7-33	Room 703-baseboard	ND
7-34	Room 703-floor	ND
7-703-69	Room 703-AC supply	ND
7-703-70	Room 703-AC supply	ND
7-EL-71	Elevator Lobby-elevator #3-floor	ND
7-B-72	Staircase B-steps	ND
7-704-73	Electrical closet-floor	ND
7-A-74	Staircase A-vestibule	ND
7-704-75	Room 704-AC supply-southeast corner	ND
7-704-76	Room 704-AC supply-northwest corner	ND
7-704-77	Room 704-top of ceiling	ND
7-706-78	Room 706-top of ceiling tile	ND
7-704-79	Room 704A-floor by entrance door	ND
7-S-80	Supply room-floor-carpeting	ND

PLM= Polarized Light Microscopy

ND= None Detected

PLM QUALITATIVE WIPE ANALYSIS

CLIENT: NYU **PROJECT#:** NY-038-02 **DATE:** 2/25/02
LOCATION: 100 Trinity Street, 8th Floor

Sample ID#	Location of Sample	PLM Analysis
8-29	Dining area-windows	ND
8-30	Dining area-air supply	ND
8-31	Kitchen-air supply	ND
8-A-57	Staircase A-steps	ND
8-D-58	Dining room-east window-ledge	ND
8-D-59	Dining room-northeast window-ledge	ND
8-D-60	Dining room-AC supply	ND
8-D-61	Dining room-AC supply-duct	ND
8-K-62	Kitchen area-window ledge	ND
8-K-64	Kitchen area-under sink-floor sample	ND
8-EL-65	Elevator lobby-floor	ND
8-K-66	Kitchen-window, south-ledge	ND
8-K-67	Electrical closet-floor	ND

PLM= Polarized Light Microscopy

ND= None Detected

PLM QUALITATIVE WIPE ANALYSIS

CLIENT: NYU **PROJECT#:** NY-038-02 **DATE:** 2/25/02
LOCATION: 100 Trinity Street, 9th Floor

Sample ID#	Location of Sample	PLM Analysis
9-23	Stairs	ND
9-24	Room 905-air conditioner	ND
9-25	Room 907-windows	ND
9-903-037	Room 903A-floor	ND
9-903-038	Room 903-top of ceiling tile	ND
9-903-039	Room 933-southwest office-window ledge	ND
9-903-040	Room 933B, west office-window ledge	ND
9-933-41	Room 933-west side-window ledge	ND
9-933-42	Room 933-northwest side (college office) window ledge	ND
9-933-43	Room 933-north side, UFT, window ledge	ND
9-933-44	Room 933, by cabinet-carpeting	ND
9-933-45	Room 933, UFT office-carpeting	ND
9-933-46	Room 933-center AC supply	ND
9-933-47	Room 933, copy room-carpeting	ND
9-933-48	Room 933, northwest office-top of ceiling tile	ND
9-933-49	Room 933-northwest supply office-AC supply	ND
9-933-50	Room 933-northwest side-chair outside northwest office	ND
9-933-51	Room 933, UFT-chair	ND
9-933-52	Room 933-southwest office-chair	ND
9-933-53	Room 933-southwest office-chair	ND
9-914-54	Room 914-by window (northeast)-window ledge	ND
9-913-55	Room 913-chair	ND

PLM= Polarized Light Microscopy

ND= None Detected

PLM QUALITATIVE WIPE ANALYSIS

CLIENT: NYU **PROJECT#:** NY-038-02 **DATE:** 2/25/02
LOCATION: 100 Trinity Street, 10th Floor

Sample ID#	Location of Sample	PLM Analysis
10-20	Room 1002-air conditioner	ND
10-21	Room 1002-book shelf	ND
10-22	Room 1002-windows	ND
10-1002A-001	Inside room 1002A-window ledge	ND
10-1002-002	Inside room 1002A-by window-computer table	ND
10-1002-003	Inside room 1002-carpeting adjacent to entrance	ND
10-1002-004	Inside room 1002-carpeting, northwest side-floor	ND
10-1002-005	Inside room 1002-carpeting north side-floor	ND
10-1002-006	Inside room 1002-crpeting east side-floor	ND
10-1002-007	Inside room 1002-inside register by entrance	ND
10-1002-008	Inside room 1002-inside register north side	ND
10-1006-009	Room 1006-carpeting-west side	ND
10-010	Staircase B-landing	ND
10-1006-11	Room 1006-inside register-northwest office	ND
10-100612	Room 1006-inside register-west office	ND
10-1006-13	Room 1006-inside register-southwest office	ND
10-14	Inside elevator #3-elevator floor	ND
10-1003-15	Room 1003-inside register-AC diffuser	ND
10-1003-16	Room 1003-inside register-AC return diffuser	ND
10-17	Inside electrical room-floor	ND
10-1003-18	Room 1003-floor carpeting	ND
10-1001-19	Room 1001, floor-carpeting	ND
10-20	Staircase A-staircase steps	ND

PLM= Polarized Light Microscopy

ND= None Detected

PLM QUALITATIVE WIPE ANALYSIS

CLIENT: NYU **PROJECT#:** NY-038-02 **DATE:** 2/25/02
LOCATION: 100 Trinity Street, Mechanical Room (MER)

Sample ID#	Location of Sample	PLM Analysis
M-26	Top of table	ND
M-27	Pumps surface	ND
M-28	Top of light	ND
MER-22	Floor-adjacent to entrance to roof-floor	Positive
MER-23	Floor by the boiler	ND
MER-24	Corner of entrance to MER-floor	ND
MER-25	By desk-floor	ND
MER-26	By north entrance-floor	ND
MER-30	AC control panel-floor	Positive
MER-033	North side Cooling Tower-panel area	ND

PLM= Polarized Light Microscopy

ND= None Detected

PLM QUALITATIVE WIPE ANALYSIS

CLIENT: NYU **PROJECT#:** NY-038-02 **DATE:** 2/25/02
LOCATION: 100 Trinity Street, Rooftop

Sample ID#	Location of Sample	PLM Analysis
Roof-27	Cooling Tower louver-east side	ND
Roof-28	Cooling Tower louver-north side	ND
Roof-29	Cooling Tower louver-west side	Positive
Roof-31	North side-inside AH (left)	ND
Roof-32	North side inside AH (right)	Positive

PLM= Polarized Light Microscopy

ND= None Detected

PLM BULK SAMPLE ANALYSIS

CLIENT: NYU **PROJECT#:** NY-038-02 **DATE:** 2/25/02
LOCATION: 100 Trinity Street

Sample ID#	Location of Sample	PLM Analysis
10-21	Staircase B, next to railing-lot of debris	1.60% Chrysotile
MER-034	North side Cooling Tower-panel	26.70% Chrysotile
Roof-035	Drain area-west-debris	ND
Roof-036	Drain area-north-debris	<1% Chrysotile
8-B-56	Staircase B-debris	ND
9-B-63	Staircase B-railing-debris	<1% Chrysotile
7-B-68	Staircase B-railing-debris	ND
6-B-081	Staircase B-debris on railing	<1% Chrysotile

PLM= Polarized Light Microscopy

ND= None Detected

PLM QUALITATIVE WIPE ANALYSIS**CLIENT:** NYU **PROJECT#:** NY-038-02**DATE:** 2/2802**LOCATION:** 100 Trinity Street

Sample ID#	Location of Sample	PLM Analysis
01	10 th Fl.-Stair B Small Vestibule	ND
02	9 th Fl.- Stair B Small Vestibule	ND
03	8 th Fl.- Stair B Small Vestibule	ND
04	7 th Fl.- Stair B Small Vestibule	ND
05	6 th fl.- Stair B Small Vestibule	ND
06	5 th Fl.- Stair B Small Vestibule	Chrysotile
07	4 th Fl.- Stair B Small Vestibule	ND
08	3 rd Fl.- Stair B Small Vestibule	ND
09	2 nd Fl.- Stair B Small Vestibule	Chrysotile

PLM= Polarized Light Microscopy

ND= None Detected