

01



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 10-15-01
ADDRESS: 345 Chambers St., NY, NY 10282

Toll 10166A

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (struc/mm ³)	Structure Concentration (struc/cc)
							0.5-5.0 (µ)	>5.0 (µ)		
1	PIER-25 North Entrance of school	16:07	24:00	3	3	1419	0	0	<16.67	<0.0045
2	PIER-25 North Entrance of school	16:11	24:01	3	3	1410	0	0	<16.67	<0.0045

TECHNICIAN: Dimitrios M. SAKIS

ROTAMETER: KAM101

CHAIN OF CUSTODY	RECEIVED AT LAB BY: <i>[Signature]</i>
	SAMPLE CONDITION UPON RECEIPT:
	DATE/TIME: 10/16/01

ANALYST: *[Signature]*

DATE RECEIVED: 10/16/01

RECEIVED
KAM CONSULTANTS
DATE OF ANALYSIS: 10/16/01
55-9 IN 91 100 101

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RESULTS TO (212) 941-5358

KAM CONSULTANTS

10/16/2001 08:15 FAX 7187291876

CITY_21MC100_003250522