



AMBIENT GROUP, INC.

10 Morris Avenue, Glen Cove, NY 11542
Phone: (516) 609-0009 - Fax: (516) 609-8271

Laboratory Report

AGL04033

Dust Characterization Laboratory Data Report

Client: Preventive Maintenance Inspection, Inc
Address: 318 E. 70th St
New York, NY 10021
Collected By: Client Submitted
Collected: 09/03/2002

Job Number: C/S-4033
Date Received: 09/04/2002
Date Analyzed: 09/05/2002
Job Location: 318 East 70th Street

Lab ID Field ID	Sample Location	Constituents	Percent of Sample **
0004033-001	Dust from World Trade Center	Carbon Particles	10
		Cellulose	20
		Cement Dust	30
		Chrysotile	1.5
		Fiber Glass	30
		Gravel Road Dust	8.5
			100
0004033-002	Large Paint Chip	Carbon Particles	10
		Cellulose	15
		Cement Dust	20
		Fiber Glass	40
		Gravel Road Dust	15
			100
0004033-003	Smaller Paint Chip, Backside	Carbon Particles	20
		Cellulose	10
		Cement Dust	20
		Fiber Glass	5
		Gravel Road Dust	35
		Rust	10
			100

Tarik Fato

SIGNED FOR AMBIENT GROUP, INC. BY: