


TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

20511

516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS SCA		CONTACT Hamid Savoy		SAMPLER (SIGNATURE) AL. Kazarov		DATE 7/19/02		TIME		SAMPLE(S) SEALED (YES) / NO	
PROJECT LOCATION: Stuyvesant H.S. .M.		PROJECT # M477-15217/29881		SAMPLER NAME (PRINT) AL. Kazarov		CORRECT CONTAINER(S) (YES) / NO					
SAMPLE INFORMATION:		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER									
LABORATORY #	SAMPLE #	LOCATION	AREA (FT ²)	SURFACE MATERIAL				LAB RESULT			
				WOOD	METAL	BRICK	OTHER				
	W-01	Room # 1017A, Top Univent Composid sample (Ain Daffon)	1		X			49.0			
	W-02	Room # 1017A, Bottom Univent South side (Back wall)	1		X			49.0			
	W-03	Room # 801 South side Univent, Back wall	1		X			49.0			
	W-04	Room # 807 South side Univent (Back wall)	1		X			49.0			
	W-05	Room # 809 South side Univent (Back wall)	1		X			49.0			
	W-06	Room # 811 South side Right Univent (Back wall)	1		X			49.0			
	W-07	Room # 811 South side Middle Univent (Back wall)	1		X			49.0			
	W-08	Room # 811 South side Left Univent (Back wall)	1		X			49.0			
Fax results to Taylor: (912) 406-2535				TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /				COMMENTS / INSTRUCTIONS OK TAY			
RELINQUISHED BY (SIGNATURE) 		DATE 7/19/02 TIME 01:00		PRINTED NAME AL. Kazarov		RECEIVED BY (SIGNATURE) R. Drudma		DATE 7.20.02 TIME		PRINTED NAME R. Drudma	
RELINQUISHED BY (SIGNATURE)		DATE TIME		PRINTED NAME		RECEIVED BY LAB (SIGNATURE)		DATE TIME		PRINTED NAME	

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

CITY_DEP_WORBY_CANNATA_SUBP_000003587

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE, FLORAL PARK, NY 11001

200711

516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS SCA		CONTACT: Hamid Savos		SAMPLER (SIGNATURE) <i>[Signature]</i>		DATE 7/19/02		TIME		SAMPLE(S) SEALED YES NO	
PROJECT LOCATION: Stuyvesand H.S.		PROJECT # M477-15217/29881		SAMPLER NAME (PRINT) AL. KACAKOV						CORRECT CONTAINER(S) YES NO	
SAMPLE INFORMATION:				MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER							
LABORATORY #	SAMPLE #	LOCATION	AREA (FT ²)	SURFACE MATERIAL				LAB RESULT			
				WOOD	METAL	BRICK	OTHER				
	W-09	Room # 826 North side Univert (back wall)	1		X			9.8			
	W-10	Room # 803 South side Right side Univert (back wall)	1		X			12.2			
	W-11	Room # 803 South side Middle Univert (back wall)	1		X			49.0			
	W-12	Room # 803 South side Left Univert (back wall)	1		X			49.0			
	W-13	Room # 805 East side Univert (back wall)	1		X			49.0			
	W-14	F/B " "						49.0			
	W-15	F/B " "						49.0			
Fax results to Taylor: (212) 406-2535				TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY 1/1				COMMENTS / INSTRUCTIONS 6 hr TAT.			
RELINQUISHED BY (SIGNATURE) <i>[Signature]</i>		DATE 7/19/02 TIME 01:00		PRINTED NAME AL. KACAKOV		RECEIVED BY (SIGNATURE) R. Droukina		DATE 7.20.01 TIME		PRINTED NAME R. Droukina	
RELINQUISHED BY (SIGNATURE)		DATE		PRINTED NAME		RECEIVED BY LAB (SIGNATURE)		DATE		PRINTED NAME	
		TIME						TIME			

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

CITY_DEP_WORBY_CANNATA_SUBP_000003588