



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 1

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other 1100

PROJECT INFORMATION

1. Client: <u>NYC-SCA</u>		2. Project Name <u>Stuyvesant High School</u>		3. Project #		4. Project Monitor: <u>M. BALOTA</u>		4c. Rotameter Number: <u>HD-090</u>	
		2a. Project Address <u>345 Chambers Street</u>		3a. Task #		4a. Air Sampler: <u>JUNIOR PHILLIPS</u>			
5. Date: <u>09.26.01.</u>		6. Abatement Location: <u>Chambers St-side walk</u> <u>Outside the building</u>		7. ☒ PCM (0.8 micron MCE) Cassette/Filter Manufacture <u>Mulh-Metries</u> Lot # <u>915</u>		8. ☐ TEM (0.45 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		9. Type: a. ☐ Background b. ☒ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
01				Field Blank								0/100	
02				Field Blank								0/100	
03	872		V	Chambers Street-side walk South West corner	12.30	14.30	120	10.0	10.0	10.0	1200.	3/100	<0.004
04	903		V	Chambers Street-side walk Intersection with North End Ave.	12.31	14.31	120	10.0	10.0	10.0	1200.	1/100	<0.004
05	915		V	Chambers Street-side walk Left side of main Entrance	12.33	14.33	120	10.0	10.0	10.0	1200.	1/100	<0.004
06	886		V	Chambers Street-side walk Right side of main Entrance	12.34	14.34	120	10.0	10.0	10.0	1200.	2/100	<0.004
07	925		V	Chambers Street-side walk South East corner	12.35	14.35	120	10.0	10.0	10.0	1200.	3/100	<0.004

CHAIN OF CUSTODY

18. Relinquished By:		19. Received By:		20. Date:	21. Time:
I <u>M. Balota</u>		<u>Rhoza</u>		<u>09/26/01</u>	<u>1100</u>
II					
III					

26. ATC Project Manager: <u>Remi Sanchez</u>		27. Result To: <u>Remi Sanchez</u> Beeper/Phone #'s <u>ATC ext 283</u>	
---	--	---	--

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:		23. Date:	24. Time:	25. Microscope Make/Serial # <u>0111111 0111111</u> ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: <u>Rhoza</u>		<u>09/26/01</u>	<u>2125</u>	
b. QC By:				
c. Lab Batch #: <u>97136</u>				
28. Comments:				Analysis Methodology ☒ PCM - NIOSH 7400A ☐ TEM - AHERA

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

CITY_DEP_WORRY_CANNATA_SUBP_000001745