

18/23/2001 22:25 212-587-8495
OCT 02 2001 08:33 FR SCIENTIFIC LABS

MURRAY HILL PROPERTY
2126793114 TO 6252840

PAGE 02



SCIENTIFIC LABORATORIES, INC.

117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

10.01.01

PLM Bulk Asbestos Report

Hillmann Environmental Company, Inc. Date Received 10/01/2001 SciLab Job No. 201101060
Attn: Mike Nehlsen Date Examined 10/01/2001 P.O. # Y1-3523
1600 Rt. 22 East Page 1 of 2
Union, NJ 07083
RE: Y1-3523; GAB Robins North America Inc.; 22 Cortland St.

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
MN-01	201101060-01	Yes	<1.0% ^{2.1}
Location: 9th Floor At Window Adj Corner Office			
Description: Grey, Heterogeneous, Debris			
Asbestos Types: Chrysotile 0.5 %			
Other Material: Cellulose 10. %, Fibrous glass 50. %, Non-fibrous 39.5 %			
MN-02	201101060-02	Yes	1.5 % ^{2.1}
Location: 9th Floor On Chair NW Corner Office			
Description: Grey, Heterogeneous, Debris			
Asbestos Types: Chrysotile 1.5 %			
Other Material: Cellulose 15. %, Fibrous glass 40. %, Non-fibrous 43.5 %			
MN-03	201101060-03	Yes	2.7 % ^{2.1}
Location: 9th Floor On Desk Center Area			
Description: Grey, Heterogeneous, Debris			
Asbestos Types: Chrysotile 2.7 %			
Other Material: Cellulose 3. %, Fibrous glass 30. %, Non-fibrous 64.3 %			
MN-04	201101060-04	Yes	1.2 % ^{2.1}
Location: 9th Floor West Side Window, Adj Window			
Description: Grey, Heterogeneous, Debris			
Asbestos Types: Chrysotile 1.2 %			
Other Material: Cellulose 20. %, Fibrous glass 30. %, Non-fibrous 48.8 %			
MN-06	201101060-05	Yes	<1.0% ^{2.1}
Location: 10th Floor In Convecter, Empty Room			
Description: Grey, Heterogeneous, Debris			
Asbestos Types: Chrysotile 0.75 %			
Other Material: Cellulose 3. %, Fibrous glass 20. %, Non-fibrous 76.25 %			