

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos Report

Hillmann Environmental Company, Inc. Date Received 10/09/2001 SciLab Job No. 201101831
 Attn: Mike Nehlsen Date Examined 10/10/2001 P.O. # Y2-1040
 1600 Rt. 22 East Page 1 of 15
 Union, NJ 07083 RE: Y2-1040; GAB Robins N America Inc.; 22 Courtland Street

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
1-001	201101831-01	Yes	<1.% ¹
Location: 35th Floor, Fan Room, North West Corner			
Description: Grey, Heterogeneous, Debris			
Asbestos Types: Chrysotile <1. %			
Other Material: Cellulose 12. %, Fibrous glass 35. %, Synthetic fibers 3. %, Non-fibrous >49. %			
1-002	201101831-02	Yes	<1.% ¹
Location: 34th Floor, Toll Room, North East Corner			
Description: Grey, Heterogeneous, Debris			
Asbestos Types: Chrysotile Trace			
Other Material: Cellulose 5. %, Fibrous glass 18. %, Synthetic fibers Trace, Non-fibrous 77. %			
1-003	201101831-03	Yes	<1.% ¹
Location: 34th Floor, Office, North West Corner			
Description: Grey, Heterogeneous, Debris			
Asbestos Types: Chrysotile Trace			
Other Material: Animal hair 2. %, Cellulose 10. %, Fibrous glass 10. %, Synthetic fibers Trace, Non-fibrous 78. %			
1-004	201101831-04	No	NAD ¹
Location: 34th Floor, Hallway, South East Corner Adj Stairwell			
Description: Grey, Heterogeneous, Debris			
Asbestos Types:			
Other Material: Cellulose Trace, Fibrous glass 60. %, Synthetic fibers 2. %, Non-fibrous 18. %			