



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page _____ of _____

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client: 99 church		2. Project Name: 99 church st NY NY		3. Project #: 1108-17		4. Project Monitor: Pauline's Gorky	
5. Date: 9/23/01		6. Abatement Location: SPL		7. ☒ PCM (0.6 micron MCE) Cassette/Filter Manufacturer: MMJ Lot #: 0104695		8. ☐ TEM (0.45 micron MCE) Cassette/Filter Manufacturer: X Lot #: _____	
9. Type: a. ☐ Background b. ☐ Pre-Abate		c. ☐ Abatement d. ☒ Post-Abate e. ☐ OSHA		f. ☐ Environmental g. ☐ Ambient h. ☐ Other		4c. Rotameter Number: SD-152	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. FCC
		12a. N/A	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
3-01				Field Blank								0/100	
3-02				3 PL NW corner	1655	1855	120	15	15	15	1800	3/100	<0.003
3-03				3 PL S/W corner	1656	1856	120	15	15	15	1800	2/100	<0.003
3-04				3 PL West side middle	1658	1858	120	15	15	15	1800	2/100	<0.003
3-05				3 PL South side	1659	1859	120	15	15	15	1800	2/100	<0.003
3-06				3 PL S/E corner	1700	1900	120	15	15	15	1800	2/100	<0.003

CHAIN OF CUSTODY

18. Relinquished By: I. [Signature]		19. Received By: ALACL		20. Date: 9/23/01	21. Time: 2030
II					
III					

26. ATC Project Manager: Ben Sallami	27. Result To: Ben Sallami Beeper/Phone #'s: _____
--	--

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: a. Analyzed By: MA L b. QC By: _____ c. Lab Batch #: 97079		23. Date: 9/23/01	24. Time: 2200
25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☒ Nikon Labophot 239079			
28. Comments:			

Analysis Methodology: PCM - NIOSH 7400A TEM - AHERA	
---	--

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1

CITY_21MC100_002842199

Page 1 of 1

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

1. Client: 99 Church		2. Project Name: 99 Church St NY NY		3. Project #: 4108-17		4. Project Monitor: Vicki Gustafson		4c. Rotameter Number: SD-132	
5. Date: 9/28/97		6. Abatement Location: 4 FL		7. ☒ PCM (0.5 million NCE) Cassette/Fiber Manufacturer: KIMO Lot #: 01040915		8. ☐ TEM (0.45 million NCE) Cassette/Fiber Manufacturer: Lot #: _____		9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☒ Post-Abate e. ☒ OSHA f. ☐ Environmental g. ☐ Ambient h. ☐ Other	

[illegible]

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
		9/23/11	2030
II			
III			

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By: <i>MAC L</i>	<i>9/23/01</i>	<i>22.50</i>
b. QC By:		
c. Lab Batch #: <i>97081</i>		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☒ Nikon Labophot 239079

28. Comments:

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

NY-1 (1/01)