



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page _____ of _____

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client: 99 church		2. Project Name: 99 church		3. Project #: 71108-17		4. Project Monitor: Steve August's past 11/1		4c. Rotameter Number: SD-152	
5. Date: 10/24/07		6. Abatement Location: 8 PL		7. ☒ PCM (0.8 micron MCE) Cassette/Filter Manufacture: MATB Lot #: 01032915		8. ☐ TEM (0.45 micron MCE) Cassette/Filter Manufacture: X Lot #: _____		9. Type: a ☐ Background b ☐ Pre-Abate c ☐ Abatement d ☐ Post-Abate e ☐ OSHA f ☐ Environmental g ☒ Ambient h ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min)			15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc F/CC
		12a. IWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
8-1				Field Blank								0/100	
				Field Blank									
8-2		✓		North side	1900	2100	120	15	15	15	1800	2/100	40.003
8-3		✓		West side	1902	2102	120	15	15	15	1800	1/100	40.003
8-4		✓		South side	1904	2104	120	15	15	15	1800	1/100	40.003
8-5		✓		S/W side	1907	2107	120	15	15	15	1800	1.5/100	40.003
8-6		✓		East side	1910	2110	120	15	15	15	1800	1/100	40.003

CHAIN OF CUSTODY

18. Relinquished By: [Signature]		19. Received By: A. Elbert		20. Date: 10/25/07	21. Time: 7:00 PM
26. ATC Project Manager: Ben Sallanji		27. Result To: Ben Sallanji Beeper/Phone #'s: _____			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: a. Analyzed By: A. Elbert		23. Date: 10.25.07	24. Time: 13:30	25. Microscope Make/Serial #: Olympus 1025 ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
b. QC By: _____				
c. Lab Batch #: 97659				
28. Comments:				Analysis Methodology: PCM - NIOSH 7400A TEM - AHERA

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page _____ of _____

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____
PROJECT INFORMATION

1. Client: 99 Church		2. Project Name: 99 Church NY		3. Project #: EL108-17		4. Project Monitor: Amst's Gustaf		4c. Rotameter Number: SD-152	
5. Date: 10/24/01		6. Abatement Location: 9 FC		7. ☒ PCM (0.8 micron MCE) Cassette/Filter Manufacture: MAT Lot #: 01032915		8. ☐ TEM (0.45 micron MCE) Cassette/Filter Manufacture: / Lot #: /		9. Type: a. ☐ Background c. ☐ Abatement f. ☐ Environmental b. ☐ Pre-Abate e. ☐ OSHA h. ☐ Other	

DAILY AIR SAMPLE RECORD

10 Sample I.D. Number	11 Pump Number	12 Sample Location		12c. Sample Coordinates	13 Time (24 hrs clock)			14 Flow Rate (L/min)			15 Total Air Vol. (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc F/CC
		12a. IWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
9-1				Field Blank									
				Field Blank									
9-2		✓		North side	1640	1840	120	15	15	15	1800	1.5/100	<0.003
9-3		✓		West side	1642	1842	120	15	15	15	1800	1/100	<0.003
9-4		✓		South side	1645	1845	120	15	15	15	1800	2/100	<0.003
9-5		✓		S/W side	1647	1847	120	15	15	15	1800	2/100	<0.003
9-6		✓		East side	1650	1850	120	15	15	15	1800	1.5/100	<0.003

CHAIN OF CUSTODY

18. Relinquished By: I	19. Received By: A. Elbert	20. Date: 10/25/01	21. Time: 10:00 AM
II			
III			
26. ATC Project Manager: Ben Sallami		27. Result To: Ben Sallami Beep/Phone #'s _____	

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: A. Elbert	23. Date: 10.25.01	24. Time: 14:00	25. Microscope Make/Senal # 1025 ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: A. Elbert			
b. QC By: A. Elbert			
c. Lab Batch #: 97655			Analysis Methodology PCM - NIOSH 7400A TEM - AHERA
28. Comments			

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page _____ of _____

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____
PROJECT INFORMATION

1. Client 99 church		2. Project Name 99 church		3. Project # 7108-17	4. Project Monitor Jim Austin	4c. Rotameter Number SD-152
5. Date: 10/24/01		6. Abatement Location: 10 FC		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture Lot # 0032915	8. ☐ TEM (0.45 micron MCE) Cassette/Filter Manufacture Lot # X	9. Type a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement ☒ Post-Abate e. ☒ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min)			15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc F/CC
		12a. IWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
10-1				Field Blank								0/100	
				Field Blank									
10-2				North side	1420	1620	120	15	15	15	1800	1/100	<0.003
10-3				West side	1422	1622	120	15	15	15	1800	2/100	<0.003
10-4				South side	1425	1625	120	15	15	15	1800	1/100	<0.003
10-5				S/W side	1427	1627	120	15	15	15	1800	1/100	<0.003
10-6				East side	1430	1630	120	15	15	15	1800	1.5/100	<0.003

CHAIN OF CUSTODY

18. Returned By: A. Elbert	19. Received By: A. Elbert	20. Date: 10/25/01	21. Time: 7:00 PM
II			
III			

26. ATC Project Manager: Ben Sallami	27. Result To: Ben Sallami
Beeper/Phone #'s _____	

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: a. Analyzed By: A. Elbert	23. Date: 10/25/01	24. Time: 14:30	25. Microscope Make/Serial #: Olympus 1025 ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
b. QC By:			
c. Lab Batch # 97656			
28. Comments:			Analysis Methodology: PCM - NIOSH 7400A TEM - AHRA

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page _____ of _____

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client: 99 church		2. Project Name 99 church NY NY		3. Project # 1108-17		4. Project Monitor Tim Anastasiou		4c. Rotameter Number SD-132	
5. Date: 10/24/01		6. Abatement Location: 4 FC		7. ☒ PCM (0.8 micron MCE) Cassette/Filter Manufacture: MHI Lot #: 2052915		8. ☐ TEM (0.45 micron MCE) Cassette/Filter Manufacture:  Lot #: 		9. Type: a ☐ Background b ☐ Pre-Abate c ☐ Abatement d ☐ Post-Abate e ☐ OSHA f ☐ Environmental g ☒ Ambient h ☐ Other	

DAILY AIR SAMPLE RECORD

[illegible]

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I <i>V.A.</i>			
II	<i>A. Elbert</i>	<i>10/25/11</i>	<i>7:00 PM</i>
III			

26. ATC Project Manager: <i>Ben Sallami</i>	27. Result To: <i>Ben Sallami</i> Beeper/Phone #'s _____
--	---

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:	25. Microscope Make/Senal #.
a. Analyzed By:	10/25/19	19:30	☐ Nikon Labophot 238913
b. QC By:			☐ Nikon Labophot 238917
c. Lab Batch #:			☐ Nikon Labophot 239079

28. Comments:	Analysis Methodology PCM - NIOSH 7400A TEM - AHERA
---------------	--

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_002842292