



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page _____ of _____

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client: 99 church st		2. Project Name: 99 Church St NY NY		3. Project #: 71108-17	4. Project Monitor: Jim Gustafson	4c. Rotameter Number: SD-132									
5. Date: 10/11/01		6. Abatement Location: SPL		7. ☒ PCM (0.8 micron MCE) Cassette/Filter Manufacture: MMD Lot #: 01045915		8. ☐ TEM (0.45 micron MCE) Cassette/Filter Manufacture: X Lot #: _____									
9. Type: <table style="width: 100%;"> <tr> <td>☐ a Background</td> <td>☒ c. Abatement</td> <td>☐ f Environmental</td> </tr> <tr> <td>☐ b Pre-Abate</td> <td>☒ d Post-Abate</td> <td>☐ g Ambient</td> </tr> <tr> <td></td> <td>☐ e OSHA</td> <td>☐ h Other</td> </tr> </table>							☐ a Background	☒ c. Abatement	☐ f Environmental	☐ b Pre-Abate	☒ d Post-Abate	☐ g Ambient		☐ e OSHA	☐ h Other
☐ a Background	☒ c. Abatement	☐ f Environmental													
☐ b Pre-Abate	☒ d Post-Abate	☐ g Ambient													
	☐ e OSHA	☐ h Other													

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc F/CC
		12a IWA	12b OWA	12c Sample Coordinates	13a Start	13b End	13c. Total	14a Start	14b End	14b. Avg			
5-1				Field Blank									
				Field Blank									
5-2		✓		SPL North side	1405	1605	120	15	15	15	1800	1/100	<0.003
5-3		✓		SPL West side	1406	1606	120	15	15	15	1800	2/100	<0.003
5-4		✓		SPL South side	1408	1608	120	15	15	15	1800	1/100	<0.003
5-5		✓		SPL S/W side	1410	1610	120	15	15	15	1800	3/100	<0.003
5-6		✓		SPL East side	1412	1612	120	15	15	15	1800	2/100	<0.003

CHAIN OF CUSTODY

18. Relinquished By: [Signature]	19. Received By: [Signature]	20. Date: 10/11/01	21. Time: 1725
II			
III			
26. ATC Project Manager: Ben Sallami		27. Result To: Ben Sallami Beeper/Phone #'s: _____	

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: [Signature]	23. Date: 10/11/01	24. Time: 1845	25. Microscope Make/Serial #: OLYMPUS CH2100S
a. Analyzed By: [Signature]	☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079		
b. QC By:			
c. Lab Batch #:	97329		
28. Comments:			Analysis Methodology: ☒ PCM - NIOSH 7400A ☐ TEM - AHERA

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_002842321



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page _____ of _____

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____
PROJECT INFORMATION

1. Client: 99 Church		2. Project Name: 99 Church St NY NY		3. Project #: 1108-17		4. Project Monitor: Steve Austis/USC/		4c. Rotameter Number: SD-132	
5. Date: 10/1/01		6. Abatement Location: GFC		7. ☒ PCM (0.8 micron MCE) Cassette/Filter Manufacture: MMS Lot #: 01043915		8. ☐ TEM (0.45 micron MCE) Cassette/Filter Manufacture: [Signature] Lot #: _____		9. Type: a. ☐ Background d. ☒ Post-Abate b. ☐ Pre-Abate e. ☐ OSHA	
								f. ☐ Environmental g. ☐ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min)			15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
6-1				Field Blank									
				Field Blank									
6-2		✓		GFC North side.	910	1110	120	15	15	15	1800	6/100	<0.003
6-3		✓		GFC West side	911	1111	120	15	15	15	1800	3/100	<0.003
6-4		✓		GFC South side	914	1114	120	15	15	15	1800	4/100	<0.003
6-5		✓		GFC S/W side	915	1115	120	15	15	15	1800	3/100	<0.003
6-6		✓		GFC East side.	917	1117	120	15	15	15	1800	3/100	<0.003

CHAIN OF CUSTODY

18. Relinquished By: [Signature]	19. Received By: [Signature]	20. Date: 10/1/01	21. Time: 1725
II			
III			

26. ATC Project Manager: Ben Sallami	27. Result To: Ben Sallami Beeper/Phone #'s: _____
--	--

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: [Signature]	23. Date: 10/1/01	24. Time: 19:15	25. Microscope Make/Serial #: OLYM Plus 100/100x ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: [Signature]			
b. QC By:			
c. Lab Batch #:	97380		

28. Comments:	Analysis Methodology: ☒ PCM - NIOSH 7400A ☐ TEM - AHERA
---------------	--

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_002842322



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page _____ of _____

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____
PROJECT INFORMATION

1 Client: <u>79 Church st</u>		2. Project Name: <u>99 Church St NY NY</u>		3. Project #: <u>7108-17</u>	4. Project Monitor: <u>Tim Gustislovsky</u>	4c Rotameter Number: <u>SD-132</u>
5 Date: <u>10/10/1</u>		6 Abatement Location: <u>7 FL</u>		7. ☒ PCM (0.8 micron MCE) Cassette/Filter Manufacture: <u>MMT</u> Lot # <u>01045915</u>	8. ☐ TEM (0.45 micron MCE) Cassette/Filter Manufacture: <u>[X]</u> Lot # _____	9 Type: a ☐ Background ☒ Post-Abate b ☐ Pre-Abate c ☐ Abatement e ☐ OSHA f ☐ Environmental g ☐ Ambient h ☐ Other

DAILY AIR SAMPLE RECORD

10 Sample I D Number	11 Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14 Flow Rate (L/min)			15 Total Air Vol. (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc F/CC
		12a. IWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
7-1				Field Blank								0/100	
				Field Blank									
7-2		V		<u>7 FL North side</u>	1020	1220	120	15	15	15	1800	3/100	<0.003
7-3		V		<u>7 FL West side</u>	1021	1221	120	15	15	15	1800	4/100	<0.003
7-4		V		<u>7 FL South side</u>	1023	1223	120	15	15	15	1800	4/100	<0.003
7-5		V		<u>7 FL S/W side</u>	1025	1225	120	15	15	15	1800	2/100	<0.003
7-6		V		<u>7 FL East side</u>	1027	1227	120	15	15	15	1800	3/100	<0.003

CHAIN OF CUSTODY

18 Relinquished By: <u>[Signature]</u>	19. Received By: <u>[Signature]</u>	20. Date: <u>10/10/1</u>	21. Time: <u>1830</u>
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22 Lab Name: <u>[Signature]</u>	23. Date: <u>10/10/1</u>	24. Time: <u>2010</u>	25 Microscope Make/Serial # <u>OLYMPUS CH21015</u> ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a Analyzed By:			
b QC By:			
c. Lab Batch #: <u>97366</u>			

26. ATC Project Manager: <u>Ben Sella mi</u>	27 Result To: <u>Ben Sella mi</u> Beeper/Phone #'s _____
---	---

28 Comments:

Analysis Methodology
☒ PCM - NIOSH 7400A
☐ TEM - AHERA

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY 1 (1/01)



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page _____ of _____

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1 Client <u>79 Church St</u>		2 Project Name <u>99 Church St NY NY</u>		3 Project # <u>71108-17</u>		4 Project Monitor <u>Tim Anastasiadis</u>		4c Rotameter Number <u>81-132</u>	
5 Date <u>10/10/1</u>		6 Abatement Location <u>8 FC</u>		7 ☒ PCM (0.8 micron MCE) Cassette/Filter Manufacture <u>MMI</u> Lot # <u>01095915</u>		8 ☐ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>X</u> Lot # <u>X</u>		9. Type: a ☐ Background c ☐ Abatement b ☐ Pre-Abate d ☒ Post-Abate e ☐ OSHA f ☐ Environmental g ☐ Ambient h ☐ Other	

DAILY AIR SAMPLE RECORD

10 Sample I.D. Number	11 Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min)			15 Total Air Vol. (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc. F/L
		12a. IWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b Avg			
8-1				Field Blank								0/100	
				Field Blank									
8-2		V		8 FC North side	1040	1240	120	15	15	15	1800	4/100	<0.003
8-3		V		8 FC West side	1042	1242	120	15	15	15	1800	2/100	<0.003
8-4		V		8 FC South side	1044	1244	120	15	15	15	1800	3/100	<0.003
8-5		V		8 FC S/W side	1045	1245	120	15	15	15	1800	2/100	<0.003
8-6		V		8 FC East side	1047	1247	120	15	15	15	1800	2/100	<0.003

CHAIN OF CUSTODY

18 Relinquished By: <u>I</u>	19 Received By <u>R. Kogan</u>	20 Date <u>10/10/1</u>	21 Time <u>1830</u>
II			
III			

26 ATC Project Manager <u>Ben Sellaoui</u>	27 Result To <u>Ben Sellaoui</u> Beeper/Phone #'s _____
---	--

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22 Lab Name <u>R. Kogan</u>	23 Date <u>10/10/1</u>	24 Time <u>1935</u>	25 Microscope Make/Serial # <u>Nikon Labophot 238913</u>
a Analyzed By			☐ Nikon Labophot 238913
b. QC By.			☐ Nikon Labophot 238917
c. Lab Batch #.			☐ Nikon Labophot 239079

28 Comments.	Analysis Methodology ☒ PCM - NIOSH 7400A TEM - AHERA
--------------	--

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY 1 (1/01)

CITY_21MC100_002842324