

SciLab Job #: 201091891

Client Name Colden Corporation

Table I
Summary of Transmission Electron Microscopy (TEM) Results for Asbestos (air)

01204; Pace University; 41 Park Row-Manhattan, NY

SciLab Sample #	Client Sample #	Dilution Factor	Air Filtered (liters)	Area Analyzed (sq. mm.)	* Analytical Sensitivity (struc/cc air)	Asbestos Structures Detected			Structure Density (struc/sq. mm.)		Structure Concentration (struc/cc air)		Type of Asbestos
						0.5-5.0	>5.0	Total	>5.0	Total	>5.0	Total	
01	01204-17 1st Floor, Lobby, By Security Desk		1074	.08	0.0045	0.0	0.0	0.0	<12.5	<12.5	<0.0045	<0.0045	NSD
02	01204-18 16th Floor, At Reception Desk,		1194	.08	0.0040	0.0	0.0	0.0	<12.5	<12.5	<0.0040	<0.0040	NSD
03	01204-19 9th Floor, Seating Area for Dean's Offices		1029	.08	0.0047	0.0	0.0	0.0	<12.5	<12.5	<0.0047	<0.0047	NSD
04	01204-20 3rd Floor, Classroom #302 (Dirty)		1156	.08	0.0042	0.0	0.0	0.0	<12.5	<12.5	<0.0042	<0.0042	NSD
05**	01204-21 Blank #1												

* concentration represented by the detection of 1 structure

** not analyzed

NSD: No Asbestos Structures Detected

Reviewed By: ; Analyzed By: 

Aleksandr Barengolts

Date: 9/15/01

NVLAP#: 200546-0

CITY_21MC100_002849909