

Client Name Colden Corporation

Table I
Summary of Transmission Electron Microscopy (TEM) Results for Asbestos (air)
 01204; Pace University; 1 Pace Plaza - Manhattan, NY Campus / AMBIENT

SciLab Sample #	Client Sample #	Dilution Factor	Air Filtered (liters)	Area Analyzed (sq. mm.)	* Analytical Sensitivity (struc/cc air)	Asbestos Structures Detected (Microns)			Structure Density (struc/sq. mm.)		Structure Concentration (struc/cc air)		Type of Asbestos
						0.5-5.0	>5.0	Total	>5.0	Total	>5.0	Total	
01	01201-01 East Tower, 7th Floor, North Side Lounge, Residential		1283	.07	0.0043	0.0	0.0	0.0	<14.3	<14.3	<0.0043	<0.0043	NSD
02	01201-02 East Tower, 14th Floor, South Side Lounge, Residential		1241	.07	0.0044	0.0	0.0	0.0	<14.3	<14.3	<0.0044	<0.0044	NSD
03	01201-03 West Tower, 5th Floor, Classroom #510, HVAC #5		1265	.07	0.0046	0.0	0.0	0.0	<14.3	<14.3	<0.0046	<0.0046	NSD
04	01201-04 East Tower, 3rd Floor, Classroom #303, AC #4		1215	.07	0.0045	0.0	0.0	0.0	<14.3	<14.3	<0.0045	<0.0045	NSD
05	01201-05 1st Floor, West Side Rear of Admissions, AC #9		1122	.07	0.0049	0.0	0.0	0.0	<14.3	<14.3	<0.0049	<0.0049	NSD
06	01201-06 B-Level, Lobby Area, AC #2		1268	.07	0.0043	0.0	0.0	0.0	<14.3	<14.3	<0.0043	<0.0043	NSD
07	01201-07 Outdoors, East Side Main Entrance 10' From Doors		2185	.04	0.0044	0.0	0.0	0.0	<25	<25	<0.0044	<0.0044	NSD
08	01201-08 5th Floor, West Side North Side Hall Center, HVAC #1		1127	.07	0.0049	0.0	0.0	0.0	<14.3	<14.3	<0.0049	<0.0049	NSD
09	01201-09 5th Floor, West Side South Side Hall Center, HVAC #2		1215	.07	0.0045	0.0	0.0	0.0	<14.3	<14.3	<0.0045	<0.0045	NSD
10**	01201-10 Blank #1												

* concentration represented by the detection of 1 structure

** not analyzed

NSD: No Asbestos Structures Detected

Reviewed By: Analyzed By: 

Alexander Barenholtz

Date: 9/15/01

NVLAP#: 200546-0

CITY_21MC100_002849942