



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 2

TURNAROUND TIME

☒ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

OBJECT INFORMATION

Client <i>Related project</i>		2. Project Name <i>225 Rector Pl</i>		3. Project #		4. Project Monitor <i>R. Hester</i>		4c. Rotameter Number	
		2a. Project Address <i>225 Rector Pl</i>		3a. Task #		4a. Air Sampler <i>R. Hester</i>		<i>HP-60</i>	
Date <i>5-01</i>		6. Abatement Location <i>Roof</i>		7. ☒ PCM (0.8 micron MCE) Cassette/Filter Manufacture <i>Nuclepore</i> Lot # _____		8. ☐ TEM (0.45 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		9. Type a. ☐ Background c. ☐ Abatement b. ☐ Pre-Abate d. ☒ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☐ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

Sample I.D. Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min)			15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
01				Field Blank								0/100	
02				Field Blank								0/100	
03		✓		North West side of large roof	3:00	5:00	120	15.0	15.0	15.0	1500	2/100	<0.003
04		✓		East side of large roof	3:01	5:01	120	15.0	15.0	15.0	1500	1/100	<0.003
05		✓		South side of large roof	3:02	5:02	120	15.0	15.0	15.0	1500	1/100	<0.003
06		✓		West side of parking roof	3:04	5:04	120	15.0	15.0	15.0	1500	1/100	<0.003
07		✓		South West side of roof	3:05	5:05	120	15.0	15.0	15.0	1500	2/100	<0.003
08		✓		Center of the parking roof	3:06	5:06	120	15.0	15.0	15.0	1500	3/100	<0.003

CHAIN OF CUSTODY

Relinquished By: <i>R. Hester</i>	19. Received By: <i>R. Hester</i>	20. Date: <i>10/25/01</i>	21. Time: <i>2:40</i>

ATC Project Manager: <i>T. Berkhardt</i>	27. Result To: _____ Beeper/Phone #'s <i>212-945-3768</i>
---	--

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name <i>R. Hester</i>	23. Date <i>10/25/01</i>	24. Time <i>2:15</i>	25. Microscope Make/Serial # <i>Nikon Labophot 238913</i> ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By:			
b. QC By:			
c. Lab Batch #: <i>97277</i>			28. Comments:

Analysis Methodology

☒ PCM - NIOSH 7400A
☐ TEM - AHERA

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY 1 (1/01)

CITY_DEP_WORBY_CANNATA_SUBP_000002899



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 2

TURNAROUND TIME

☒ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client <u>Rehabited project</u>		2. Project Name <u>225 Rector PL</u>		3. Project #		4. Project Monitor <u>Ruben Acosta</u>		4c. Rotameter Number.	
		2a. Project Address <u>225 Rector PL</u>		3a. Task #		4a. Air Sampler <u>R. Acosta</u>		4b. Rotameter Number <u>HP-100</u>	
5. Abatement Location <u>5-01 MECHANIC ROOF</u>		7. ☒ PCM (0.8 micron MCE) Cassette/Filter Manufacture <u>Nuclepore</u> Lot # _____		8. ☐ TEM (0.45 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		9. Type: a. ☐ Background b. ☐ Pre-Abate		c. ☐ Abatement d. ☒ Post-Abate e. ☐ OSHA	
						f. ☐ Environmental g. ☐ Ambient h. ☐ Other			

LABORATORY AIR SAMPLE RECORD

Sample ID Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
09		✓		South East side of mechanic roof	3:09	5:09	120	15.0	15.0	15.0	1800	1/100	<0.003
10		✓		by the middle of mechanic roof	3:09	5:09	120	15.0	15.0	15.0	1800	2/100	<0.003
11		✓		East side of mechanic roof	3:10	5:10	120	15.0	15.0	15.0	1800	4/100	<0.003

CHAIN OF CUSTODY

19. Relinquished By: <u>R. Acosta</u>	19. Received By: <u>R. Acosta</u>	20. Date: <u>10/05/01</u>	21. Time: <u>21:40</u>

ATC Project Manager:

27. Result To: <u>Burkhardt</u>	Beeper/Phone #'s <u>212-945-3765</u>
------------------------------------	--------------------------------------

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>R. Acosta</u>	23. Date: <u>10/05/01</u>	24. Time: <u>22:15</u>	25. Microscope Make/Serial # ☒ Olympus CH21015 ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: <u>R. Acosta</u>			
b. QC By: <u>1</u>			
c. Lab Batch # <u>97277</u>			Analysis Methodology ☒ PCM - NIOSH 7400A ☐ TEM - AHERA
28. Comments			

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

CITY_DEP_WORBY_CANNATA_SUBP_000002900