NYC 9/11 Public Portal Document

PHS

Parker House Services, Inc.

14 Leewood Circle
Eastchester, NY 10709
(914) 337-0229
Fax (914) 337-4955

October 8, 2001

Milford Management
155 West 68th Street
New York, NY 10023

Attn: Robert Gross

Re: Results of Air Testing @ Liberty Court, View, Terrace & House

In accordance with protocols recently established and in full compliance with the NYC Asbestos Rules and Regulations, Title#15, Chapter#1, ambient air monitoring was conducted at the subject locations. The **final** results of said testing for **Thursday October 4, 2001** were as follows:

LOCATION	SAMPLE#	TOTAL	FINALS
377 Rector Pl - Inside Lobby	1004-01-F	<0.0049	NSD
" " Outside Bldg.	1004-02-F	<0.0049	NSD
" " Inside 8th Hall	1004-03-F	<0.0049	NSD
380 Rector Pl - Inside Lobby	1004-04-F	<0.0049	NSD
" " Outside Bldg.	1004-05-F	<0.0049	NSD
" " Inside 8th Hall	1004-06-F	<0.0049	NSD
99 Battery Pl - Inside Lobby	1004-07-F	<0.0049	NSD
" " Outside Bldg.	1004-08-F	<0.0049	chrysotile
200 Rector Pl – Inside No.Lobby	1004-09-F	<0.0049	NSD
" " Inside So.Lobby	1004-10-F	<0.0049	NSD
" " Outside Bldg.	1004-11-F	<0.0049	NSD
" " Inside 8th Hall	1004-12-F	<0.0049	NSD
377 Rector Pl – Inside Apt.#2E	1004-16-F	<0.0049	NSD
99 Battery Pl – Inside 8th Hall	1004-17-F	<0.0049	NSD

(N.B. NSD = No Structures Detected)
All samples were analyzed by Transmission Electron Microscopy, Scilab ELAP#11480, NVLAP#200546-0.
All final samples **pass final clearance levels. No further action is necessary.**

Very truly yours,
Michael LaCommare
Michael LaCommare-President