



Environmental Monitoring & Consulting Associates

P.O. BOX 872 • SOMERVILLE, NJ 08876 • (732) 249-3005 • FAX (732) 249-3384

TO: Black Diamond LLC
88 Greenwich Street
New York, New York 10006

RE: AIRBORNE ASBESTOS ANALYSIS/88 GREENWICH STREET/NEW YORK, NEW YORK/
AREA AIR MONITORING

Airborne Fiber Analysis By Transmission Electron Microscopy
(TEM) Performed In Accordance With EPA 40 CFR Part 763 Final Rule (AHERA)

<u>DATE</u>	<u>SAMPLE/LOCATION</u>
12/14/01	88-14-001/First Floor/ Lobby/Near Elevator
12/14/01	88-14-002/Sixth Floor/ Public Corridor/Near Ele- vator
12/14/01	88-14-003/Eleventh Floor/ Public Corridor/Near Ele- vator
12/14/01	88-14-004/Eighteenth Floor/ Public Corridor/Near Ele- vator
12/14/01	88-14-005/Twenty-First Floor/ Public Corridor/Near Ele- vator



Environmental Monitoring & Consulting Associates

P.O. BOX 872 • SOMERVILLE, NJ 08876 • (732) 249-3005 • FAX (732) 249-3384

TO: Black Diamond LLC
88 Greenwich Street
New York, New York 10006

RE: AIRBORNE ASBESTOS ANALYSIS/88 GREENWICH STREET/NEW YORK, NEW YORK/
AREA AIR MONITORING

Airborne Fiber Analysis By Transmission Electron Microscopy
(TEM) Performed In Accordance With EPA 40 CFR Part 763 Final Rule (AHERA)

<u>DATE</u>	<u>SAMPLE/LOCATION</u>
12/14/01	88-14-006/Twenty-Third Floor/ Public Corridor/Near Elevator
12/14/01	88-14-007/Twenty-Sixth Floor/ Public Corridor/Near Elevator
12/14/01	88-14-008/Thirtieth Floor/ Public Corridor/Near Elevator
12/14/01	88-14-009/Thirty-Fifth Floor/ Public Corridor/Near Elevator
12/14/01	88-14-010/Thirty-Sixth Floor/ Public Corridor/Near Elevator