



Environmental Monitoring & Consulting Associates

P.O. BOX 872 • SOMERVILLE, NJ 08876 • (732) 249-3005 • FAX (732) 249-3384

TO: Black Diamond LLC
88 Greenwich Street
New York, New York 10006

RE: AIRBORNE ASBESTOS ANALYSIS/88 GREENWICH STREET/NEW YORK, NEW YORK/
AREA AIR MONITORING

Airborne Fiber Analysis By Transmission Electron Microscopy
(TEM) Performed In Accordance With EPA 40 CFR Part 763 Final Rule (AHERA)

<u>DATE</u>	<u>SAMPLE/LOCATION</u>
2/4/02	88-4-001/First Floor/ Public Corridor/Near Apartment #107
2/4/02	88-4-002/Fourth Floor/ Public Corridor/Near Apartment #407
2/4/02	88-4-003/Eighth Floor/ Public Corridor/Near Apartment #807
2/4/02	88-4-004/Twelfth Floor/Public Corridor/ Near Apartment #1207
2/4/02	88-4-005/Seventeenth Floor/Public Corridor/ Near Apartment #1707



Environmental Monitoring & Consulting Associates

P.O. BOX 872 • SOMERVILLE, NJ 08876 • (732) 249-3005 • FAX (732) 249-3384

TO: Black Diamond LLC
88 Greenwich Street
New York, New York 10006

RE: AIRBORNE ASBESTOS ANALYSIS/88 GREENWICH STREET/NEW YORK, NEW YORK/
AREA AIR MONITORING

Airborne Fiber Analysis By Transmission Electron Microscopy
(TEM) Performed In Accordance With EPA 40 CFR Part 763 Final Rule (AHERA)

<u>DATE</u>	<u>SAMPLE/LOCATION</u>
2/4/02	88-4-006/Twenty-First Floor/Public Corridor/ Near Apartment #2107
2/4/02	88-4-007/Twenty-Fourth Floor/Public Corridor/ Near Apartment #2407
2/4/02	88-4-008/Twenty-Eighth Floor/Public Corridor/ Near Apartment #2808
2/4/02	88-4-009/Thirty-First Floor/Public Corridor/ Near Apartment #3108
2/4/02	88-4-010/Thirty-Third Floor/Public Corridor/ Near Apartment #3303