



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 4

TURNAROUND TIME			
☐ 2 hrs	☐ 6 hrs	☐ 48 hrs	☐ Standard
☐ 14 hrs	☒ 24 hrs	☐ 72 hrs	☐ Other

PROJECT INFORMATION

1. Client: DEP	2. Project Name: DEP Clean-up	3. Project #: 15-23906-0002	4. Project Monitor: E. Lewanovich	4c. Retention Number: SD-006
2a. Project Address: 125 Cedar St. NY	3a. Task #: 00002			
5. Date: 10.07.02	6. Abatement Location:	7. ☒ PCM (performance) Customer Name/Job: 01283108	8. ☐ TEM (45 min) W20 Customer Name/Job: 01283108	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☐ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample ID Number	11. Pump Number	12. Sample Location		2c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Filters minus Blank	17. Fiber Conc. /ACC
		12a. NWA	12b. DMA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
PH-01		✓		13 Floor. Penthouse	16:30	22:55	385	10	10	10	3850	7/100	<0.001
PH-02		✓		---	16:32	22:56	384	10	10	10	3840	7/100	<0.001
PH-03		✓		---	16:34	22:57	383	10	10	10	3830	8/100	<0.001
PH-04		✓		---	16:36	22:58	382	10	10	10	3820	5/100	<0.001
PH-05		✓		---	16:38	22:59	381	10	10	10	3810	4/100	<0.001
12N-06		✓		12 Floor. Apartment North	16:43	23:05	382	10	10	10	3820	6/100	<0.001
12N-07		✓		---	16:45	23:06	381	10	10	10	3810	8/100	<0.001
12N-08		✓		---	16:47	23:07	380	10	10	10	3800	11/100	<0.001
12N-09		✓		---	16:49	23:08	379	10	10	10	3790	8/100	<0.001
12N-10		✓		---	16:51	23:09	378	10	10	10	3780	3/100	<0.001
12SW-11		✓		12 Floor. Apartment SW	16:56	23:12	376	10	10	10	3760	6/100	<0.001
12SW-12		✓		---	16:58	23:13	375	10	10	10	3750	7/100	<0.001

CHAIN OF CUSTODY

19. Relinquished By: E. Lewanovich	20. Received By: A. Elchert	21. Date: 10.8.2	22. Time: 11:00
II			
III			

25. ATC Project Manager: B. Sallawi	27. Report To: B. Sallawi 3a. Phone #s:
---	---

LAB INFORMATION (ATC CLAP # 10879, ATC NVLP # 1187)

22. Lab Name: PCM Lab	23. Date:	24. Time:	25. Microscope Make/Serial #: PCMA-12345678
26. Analyzed By: A. Elchert			☐ Nikon Labophot 236013
27. QC By:			☐ Nikon Labophot 236017
28. Lab Catch #:			☐ Nikon Labophot 236078
29. Comments:			Analysis Methodology: PCM - NIOSH JACCA TEM - AHERA

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_002863040



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 4

TURNAROUND TIME				
☐ 2 hrs	☐ 6 hrs	☐ 48 hrs	☐ Standard	
☐ 14 hrs	☒ 24 hrs	☐ 72 hrs	☐ Other	

PROJECT INFORMATION

1. Client: DEP	2. Project Name: DEP Clean-up	3. Project #: 15-22406-0002	4. Project Monitor: E. Lemanovich	Ac. Pollutant Number: 85-005
5. Date: 10.07.02	6. Abatement Location:	7. ☒ PCM (permanently) Cassette/Filter Number: 01283108	8. ☐ EMI (no asbestos) Cassette/Filter Number: None	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ CSHA f. ☐ Environmental g. ☐ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min)			15.	16.	17.
		12a. N/A	12b. ONA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg	Total Air Vol. (liters)	# Filters/Fields	Fiber Conc. f/20
				Field Blank									
				Field Blank									
12SW-13		✓		12 Floor Apartment SW	17:00	23:14	374	10	10	10	3740	4/100	40.001
12SE-14		✓		12 Floor Apartment SE	17:04	23:17	373	10	10	10	3730	3/100	40.001
12SE-15		✓		---	17:06	23:18	372	10	10	10	3720	4/100	40.001
12SE-16		✓		---	17:08	23:19	371	10	10	10	3710	3/100	40.001
12SE-17		✓		---	17:10	23:20	370	10	10	10	3700	5/100	40.001
12SE-18		✓		---	17:12	23:21	369	10	10	10	3690	2.5/100	40.001
11N-19		✓		11 Floor Apartment North	17:18	23:24	366	10	10	10	3660	4/100	40.001
11N-20		✓		---	17:20	23:25	365	10	10	10	3650	4/100	40.001
11N-21		✓		---	17:22	23:26	364	10	10	10	3640	2/100	40.001
11N-22		✓		---	17:24	23:27	363	10	10	10	3630	3/100	40.001
11N-23		✓		---	17:26	23:28	362	10	10	10	3620	2/100	40.001
11S-24		✓		11 Floor Apartment South	17:38	23:38	363	10	10	10	3630	2.5/100	40.001

CHAIN OF CUSTODY

18. Relinquished By: E. Lemanovich	19. Received By: A. Elbert	20. Date: 10.8.2	21. Time: 11:00
II			
III			
26. ATC Project Manager: B. Sallami	27. Result To: B. Sallami	Beepers/Phone #s:	

LAB INFORMATION (ATC ELAP # 10679, ATC NVLAP # 1:87)

22. Lab Name: PCM Lab	23. Date: 10/15/02	24. Time: 15:00
a. Analyzed By: A. Elbert		
b. QC By:		
c. Lab Batch #:	101527	
28. Comments:		
25. Microscope Make/Serial #: Photomicroscope		
☐ Nikon Labophot 2000		
☐ Nikon Labophot 2000		
Analysis Methodology: PCM - NIOSH 7400		
TEM - AHERA		

WHITE - File

YELLOW - Client Report

PINK - Lab

GOLDENROD - Field

NY-1 (10/1)



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 3 of 4

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☒ 4 hrs ☒ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION

1. Client: **DEP** 2. Project Name: **DEP Clean-up** 3. Project #: **15-22905-0001** 4. Project Manager: **E. Lemaunovich** 4c. Rotameter Number: **SP-006**
 2a. Project Address: **125 Cedar St NY 10002** 5a. Task #: **00002** 5. Date: **10.07.08** 6. Abatement Location: **Asbestos** 7. ☒ PCM (0.5 micron NCE) 8. ☒ TEM (0.45 micron NCE) 9. Type: ☐ Abatement ☐ Environmental ☐ Background ☐ Post-Abate ☐ Pre-Abate ☐ OSHA ☐ Other

DAILY AIR SAMPLE RECORD

0. Sample I.D. Number	11. Pump Number	12. Sample Location		13. Time (24 hrs clock)	14. Flow Rate (L/min)			15. Total Air Vol (liters)	16. # Fibers/Fields Mirus Blank	17. Fiber Count F/CC			
		12a. TWA	12b. DMA		14a. Start	14b. End	14c. Avg						
				Field Blank									
				Field Blank									
11S-25		✓		11 Floor Apartment South	17:34	23:36	362	10	10	10	3620	8/100	40.001
11S-26		✓		---	17:36	23:37	361	10	10	10	3610	3/100	40.001
11S-27		✓		---	17:38	23:38	360	10	10	10	3600	2/100	40.001
11S-28		✓		---	17:40	23:40	360	10	10	10	3600	5/100	40.001
10N-29		✓		10 Floor Apartment North	17:50	23:57	367	10	10	10	3670	1/100	40.001
10N-30		✓		---	17:52	23:58	366	10	10	10	3660	2/100	40.001
10N-31		✓		---	17:54	23:59	365	10	10	10	3650	2/100	40.001
10N-32		✓		---	17:56	24:00	364	10	10	10	3640	2.5/100	40.001
10N-33		✓		---	17:58	00:01	363	10	10	10	3630	6/100	40.001
10S-34		✓		10 Floor Apartment South	18:26	00:35	369	10	10	10	3690	1.5/100	40.001
10S-35		✓		---	18:28	00:36	368	10	10	10	3680	3/100	40.001
10S-36		✓		---	18:30	00:37	367	10	10	10	3670	7/100	40.001

CHAIN OF CUSTODY

18. Relinquished By: **E. Lemaunovich** 19. Received By: **A. Elheut** 20. Date: **10/8/08** 21. Time: **11:00 am**
 26. ATC Project Manager: **B. Sallawi** 27. Result To: **B. Sallawi**
 28. Result Phone #s: _____

LAB INFORMATION (ATC ELAP # 10879, ATC MLAP # 1187)

22. Lab Name: **PCMA Lab** 23. Date: **10/8/08** 24. Time: **15:00** 25. Microscope Make/Serial #: **Microscope 239313**
 a. Analyzed By: **A. Elheut** b. QC By: **A. Elheut** c. Lab Batch #: **101527**
 Analysis Methodology: **PCM - MCSH 743DA**
 ITSM - AMERA

WHITE - Fte

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY 1 (1/01)

10/11/2002 16:44 FAX 212 353 8308

ATC

015

CITY_21MC100_002863042



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 4 of 4

TURNAROUND TIME				
☐ 2 hrs	☐ 8 hrs	☐ 48 hrs	☐ Standard	
☐ 4 hrs	☒ 24 hrs	☐ 72 hrs	☐ Other	

PROJECT INFORMATION

1. Client: DEP		2. Project Name: DEP Clean-up		3. Project #: 15-22906-0001		4. Project Vendor: E. Lemanovich		4c. Polarimeter Number: SD-006	
2a. Project Address: 125 Cedar St NY 10002		3a. Task #: 00002		4a. Air Sampler: E. Lemanovich		5. Date: 10.07.08		6. Abatement Location: Asbestos	
7. ☒ PCM (30 micron filter) Cassette/Filter Manufacturer: 01283103		8. ☐ TEN (40 micron filter) Cassette/Filter Manufacturer:		9. Type: a. ☐ Background b. ☐ Pre-Abate		c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA		f. ☐ Environmental g. ☐ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample ID Number	11. Pump Number	12. Sample Location		12c. Sample Description	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (ft³)	16. # Fibers/Fields (100x Blank)	17. Fiber Count /CC
		12a. WFA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
105-37		✓		10 Floor Apartment South	16:32	00:38	366	10	10	10	3660	5/100	<0.002
105-38		✓			18:34	00:39	365	10	10	10	3650	4/100	<0.001
A-39			✓	13 Floor Hall Elevator	19:12	01:20	368	10	10	10	3680	14/100	0.002
A-40			✓	Laundry room	19:15	01:21	366	10	10	10	3660	11/100	0.001
A-41			✓	12 Floor Hall Elevator	19:20	01:25	365	10	10	10	3650	13/100	0.002
A-42			✓	Laundry room	19:22	01:26	364	10	10	10	3640	8/100	<0.001
A-43			✓	Staircase Between 11-12 floor	19:24	01:30	366	10	10	10	3660	7/100	<0.001
A-44			✓	11 Floor Hall Elevator	19:34	01:35	361	10	10	10	3610	19/100	0.003
A-45			✓	10 Floor Laundry room	19:48	01:50	362	10	10	10	3620	7/100	<0.001
A-46			✓	Staircase Between 9-10 floor	19:51	01:55	364	10	10	10	3640	20/100	0.003
A-47			✓	10 Floor Hall Elevator	19:53	01:58	365	10	10	10	3650	12/100	0.002
48, 49, 50, 51				Blanks								0/100/0/100	0/100/0/100

CHAIN OF CUSTODY

18. Released By: E. Lemanovich		19. Received By: A. Elbert		20. Date: 10.8.2	21. Time: 4:45
II					
III					
26. ATC Project Manager: B. Sallemi		27. Result To: B. Sallemi Beeper/Phone #s:			

LAB INFORMATION (ATC ELAP # 10879, ATC NYLAP # 1187)

22. Lab Name: PCM Lab		23. Date: 10/08/08		24. Time: 15:00	
a. Analyzed By: A. Elbert		b. QC By:		c. Lab Batch #: 101527	
25. Microscope Make/Serial #: Nikon Labophot 238913		25. Microscope Make/Serial #: Nikon Labophot 238917		25. Microscope Make/Serial #: Nikon Labophot 238079	
28. Comments:		Analysis Methodology: PCM - NIOSH 7400A TEM - AHERA			

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)