



AIR MONITORING DATA AND

CHAIN OF CUSTODY FORM

Page 1 of 2

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Plus

ECT INFORMATION

1. Project Name <u>PS 234M</u>	3. Project # <u>84150-84167</u>	4. Project Monitor: <u>MARK NAKHUMOVICH</u>	4c. Rotameter Number: <u>HP107</u>
2a. Project Address <u>242 Greenwich St, NY, NY 10007</u>	4b. Air Sampler: <u>MARK NAKHUMOVICH</u>		
5. G-Reference Location: <u>4-9 ENTIRE</u>	7. ☐ PCM (0.5 micron MCE) Cassette/Filter Manufacturer: _____ Lot #: _____	8. ☒ REM (0.45 micron MCE) Cassette/Filter Manufacturer: _____ Lot #: _____	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

AIR SAMPLE RECORD

Sample ID number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. /
		12a. NYA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
16				Field Blank									
17				Field Blank									
01				First Floor-hallway	6:56	10:57	241	8.0	8.0	8.0	1928		
02				Cafeteria	6:58	10:59	241	8.0	8.0	8.0	1928		
03				Gymnasium	7:00	11:02	242	8.0	8.0	8.0	1936		
04				Auditorium	7:04	11:06	242	8.0	8.0	8.0	1936		
05				North playground	7:06	11:07	241	8.0	8.0	8.0	1928		
06				West playground	7:08	11:09	241	8.0	8.0	8.0	1928		
07				Roof-South PART	7:12	11:12	240	8.0	8.0	8.0	1920		
08				First Floor-hallway	10:57	14:57	240	8.0	8.0	8.0	1920		
09				North playground	10:07	15:07	240	8.0	8.0	8.0	1920		
10				West playground	11:09	15:09	240	8.0	8.0	8.0	1940		
11				Roof-South PART	11:12	15:12	240	8.0	8.0	8.0	1920		
12				Classroom #211	15:30	19:30	240	8.0	8.0	8.0	1920		

CHAIN OF CUSTODY

19. Received By: <u>[Signature]</u>	20. Date: <u>4.9.2</u>	21. Time: <u>9:00</u>
22. Project Manager: <u>Y. Efsthion</u>	23. Project Name: <u>11/11/11</u>	

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>ATC ELAP</u>	23. Date: <u>4/10</u>	24. Time: <u>11:00</u>
a. Analyzed By: <u>[Signature]</u>		
b. QC By:		
c. Lab Data #:		
25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079		

CITY_21MC100_002866458

Page 2 of 2

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other 200

7362-

1. Project Name PS 234 M		3. Project # K1584-0823		4. Project Monitor: MARK NAKHUMOVICH		4c. Rotameter Number: HP107	
2a. Project Address 242 Greenwich St, NY, NY 10007		4b. Air Sampler: MARK NAKHUMOVICH					
5. Monitoring Location: ENTIRE		7. ☐ PCM (0.8 micron MC2) Cassette/Filtr Manufacturer _____ Lot # _____		8. ☒ TEM (0.45 micron MC2) Cassette/Filtr Manufacturer _____ Lot # _____		9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA	
						i. ☐ Environmental j. ☒ Ambient h. ☐ Other	

[illegible]

disposition of:	19 Received By:	20 Date:	21 Time:
	NET	4.9.2	9 PM

22. Lab Name: <u>AFC West</u>	23. Date: <u>4/10/10</u>	24. Time: <u>1100</u>	25. Microscope Make/Serial #: ☐ Nikon Labophot: 238913 ☐ Nikon Labophot: 238917 ☐ Nikon Labophot: 239079
a. Analyzed By: <u>[Signature]</u>			
b. QC By:			
c. Lab Chain #:			

CITY_21MC100_002866459

Y. EFSTATHIOU

Casey To YEFSTATHION
Beeper/Phone #s (446) 77-115

NYC-WTC_000212419