



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 2

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other PLU

ECT INFORMATION

7999

15/18

93228-93245

2. Project Name <u>PS 234M</u>		3. Project # <u>4584-0823</u>	4. Project Monitor: <u>MARK NAKHUMOVICH</u>	4c. Rotameter Number: <u>HP107</u>
2a. Project Address <u>242 Greenwich St, NY, NY 10007</u>		4b. Air Sampler: <u>MARK NAKHUMOVICH</u>		
6/7	6. ~~Asbestos~~ Location: <u>ENTIRE</u>	7. ☐ PCM (0.3 micron MCE) Cartridge/Fiber Manufacturer: Lot #	8. ☒ TEM (0.45 micron MCE) Cartridge/Fiber Manufacturer: <u>MME</u> Lot # <u>01205916</u>	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA
		f. ☐ Environmental g. ☒ Ambient h. ☐ Other		

AIR SAMPLE RECORD

Sample ID number	Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol (liters)	16. # Fibers/Filters minus Blank	17. Fiber Conc
		12a. HWA	12b. DWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
16				Field Blank									
17				Field Blank									
01				First Floor - hallway	7:05	11:05	240	8.0	8.0	8.0	1920		
02				Cafeteria	7:07	11:07	240	8.0	8.0	8.0	1920		
03				Gymnasium	7:09	11:10	241	8.0	8.0	8.0	1928		
04				Auditorium	7:11	11:12	241	8.0	8.0	8.0	1928		
05				North playground	7:13	11:14	241	8.0	8.0	8.0	1928		
06				West playground	7:15	11:17	242	8.0	8.0	8.0	1936		
07				Roof - South PART	7:17	11:19	242	8.0	8.0	8.0	1936		
08				First Floor - hallway	11:05	15:05	240	8.0	8.0	8.0	1920		
09				North playground	11:14	15:14	240	8.0	8.0	8.0	1920		
10				West playground	11:17	15:17	240	8.0	8.0	8.0	1920		
11				Roof - South PART	11:19	15:19	240	8.0	8.0	8.0	1920		
12				Classroom # 201	16:00	20:00	240	8.0	8.0	8.0	1920		

CHAIN OF CUSTODY

Requested By	19. Received By:	20. Date:	21. Time:
	<u>M. Gray</u>	<u>6.7.02</u>	<u>21:30</u>

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 11871)

22. Lab Name:	<u>FEU</u>	23. Date:	24. Time:	25. Microscope Make/Serial #:
a. Analyzed By:	<u>MCW</u>	<u>6/8</u>	<u>2:00</u>	☐ Nikon Labophot 238910
b. QC By:				☐ Nikon Labophot 238910
c. Use Case #:				☐ Nikon Labophot 238910

18. Date/Time:

Y. Efsthion

19. Received By:

Y. Efsthion

20. Date/Time:

21. Date/Time:

CITY_21MC100_002852370



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 2

TURNAROUND TIME

☐ 2 hrs ☐ 5 hrs ☐ 40 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other 1

LECT INFORMATION

1. Project Name PS 234M	3. Project # K4584-0823	4. Project Monitor: MARK NAKHUMOVICH		4c. Polarimeter Number HP107
		4b. Air Sampler: MARK NAKHUMOVICH		
2a. Project Address 242 Greenwich St, NY, NY 10007		5. Type: c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA		
6. ☒ TEM (0.45 micron MCE)	7. ☐ PCM (0.8 micron MCE)	2. ☐ Background b. ☐ Pre-Abate	f. ☐ Environmental g. ☒ Ambient h. ☐ Other	
2b. Project Location: ENTIRE		Cartridge/Fiber Manufacturer Lot #		

Y AIR SAMPLE RECORD

[illegible]

IN OF CUSTODY

Elmquist By	19 Received By:	20 Date:	21 Time:
	<i>H. Croft</i>	<i>6.7.02</i>	<i>21.30</i>

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1157)

22. Lab Name: <u>FECH</u>	23. Date: <u>6/8</u>	24. Time: <u>2:00</u>	25. Microscope Maker/Serial #: ☐ Nikon Labophot 2385 ☐ Nikon Labophot 2385 ☐ Nikon Labophot 2385
a. Analyzed By: <u>WPC</u>			
b. QC By:			
c. Lab Control:			

CITY_21MC100_002852371