NYC 9/11 Public Portal Document

LEAD-IN-DUST WIPE SAMPLE RESULTS

STUYVESANT HIGH SCHOOL SAMPLE LOCATION	LEAD CONCENTRATION ($\mu g/ft^2$)	IS 306X SAMPLE LOCATION	LEAD CONCENTRATION ($\mu g/ft^2$)
HVAC #2 - SUPPLY	174.7 $\mu g/ft^2$	AHU #7 – SUPPLY (CORRIDOR)	127.0 $\mu g/ft^2$
HVAC #2 – SUPPLY	38.2 $\mu g/ft^2$	AHU #7 – RETURN - (CORRIDOR)	87.0 $\mu g/ft^2$
HVAC #2 – RETURN	204.7 $\mu g/ft^2$	AHU #6 – SUPPLY (ATRIUM)	171.0 $\mu g/ft^2$
HVAC #1 – SUPPLY	31.3 $\mu g/ft^2$	AHU #6– SUPPLY (CORRIDOR)	18.5 $\mu g/ft^2$
HVAC #1 – RETURN	101.4 $\mu g/ft^2$	AHU #8– SUPPLY (LOCKERS)	67.1 $\mu g/ft^2$
HVAC#1 – RETURN	253.0 $\mu g/ft^2$	AHU #8 – RETURN (LOCKERS)	430.6 $\mu g/ft^2$
HVAC #1 - RETURN	139.9 $\mu g/ft^2$	AHU #10 – SUPPLY (AUDITORIUM)	41.2 $\mu g/ft^2$
HVAC #13 – RETURN	28.7 $\mu g/ft^2$	AHU #10 – RETURN (AUDITORIUM)	115.2 $\mu g/ft^2$
HVAC #8 – RETURN	26.2 $\mu g/ft^2$	AHU #11– SUPPLY (CORRIDOR)	33.4 $\mu g/ft^2$
HVAC #8 – SUPPLY	36.7 $\mu g/ft^2$	AHU #11– RETURN (CORRIDOR)	24.3 $\mu g/ft^2$
HVAC #9 - SUPPLY	27.3 $\mu g/ft^2$	AHU #9 – SUPPLY (GYM)	119.5 $\mu g/ft^2$
HVAC #9 – RETURN	<9.0 $\mu g/ft^2$	AHU #9 – RETURN (GYM)	70.5 $\mu g/ft^2$
HVAC #7 – RETURN	48.8 $\mu g/ft^2$	AHU #12 – SUPPLY (CORRIDOR)	24.0 $\mu g/ft^2$
HVAC #7 – SUPPLY	17.0 $\mu g/ft^2$	AHU #12 – RETURN (CORRIDOR)	460.5 $\mu g/ft^2$
HVAC #14 – SUPPLY	200.5 $\mu g/ft^2$	AHU #3 – SUPPLY (LIBRARY)	368.8 $\mu g/ft^2$
		AHU #3 - RETURN (LIBRARY)	466.7 $\mu g/ft^2$
		AHU #R-1 - SUPPLY (AUDITORIUM)	130.2 $\mu g/ft^2$
		AHU #1 – RETURN (AUDITORIUM)	114.6 $\mu g/ft^2$
STUYVESANT AVERAGE CONCENTRATION	89.16 $\mu g/ft^2$	IS 306X AVERAGE CONCENTRATION	159.45 $\mu g/ft^2$

NYC 9/11 Public Portal Document

ASBESTOS BULK SAMPLE RESULTS

STUYVESANT HIGH SCHOOL SAMPLE LOCATION	ANALYTICAL RESULTS	IS 306X SAMPLE LOCATION	ANALYTICAL RESULTS
HVAC #2 - SUPPLY	No Asbestos Detected	AHU #7 – SUPPLY (CORRIDOR)	No Asbestos Detected
HVAC #2 – SUPPLY	No Asbestos Detected	AHU #7 – RETURN (CORRIDOR)	No Asbestos Detected
HVAC #2 – RETURN	No Asbestos Detected	AHU #6 – SUPPLY (ATRIUM)	No Asbestos Detected
HVAC #1 – SUPPLY	No Asbestos Detected	AHU #6– SUPPLY (CORRIDOR)	No Asbestos Detected
HVAC #1 – RETURN	No Asbestos Detected	AHU #8– SUPPLY (LOCKERS)	No Asbestos Detected
HVAC#1 – RETURN	No Asbestos Detected	AHU #8 – RETURN (LOCKERS)	No Asbestos Detected
HVAC #1 - RETURN	No Asbestos Detected	AHU #10 – SUPPLY (AUDITORIUM)	No Asbestos Detected
HVAC #13 – RETURN	No Asbestos Detected	AHU #10 – RETURN (AUDITORIUM)	No Asbestos Detected
HVAC #8 – RETURN	No Asbestos Detected	AHU #11– SUPPLY (CORRIDOR)	No Asbestos Detected
HVAC #8 – SUPPLY	No Asbestos Detected	AHU #11– RETURN (CORRIDOR)	No Asbestos Detected
HVAC #9 - SUPPLY	No Asbestos Detected	AHU #9 – SUPPLY (GYM)	No Asbestos Detected
HVAC #9 – RETURN	No Asbestos Detected	AHU #9 – RETURN (GYM)	No Asbestos Detected
HVAC #7 – RETURN	No Asbestos Detected	AHU #12 – SUPPLY (CORRIDOR)	No Asbestos Detected
HVAC #7 – SUPPLY	No Asbestos Detected	AHU #12 – RETURN (CORRIDOR)	No Asbestos Detected
HVAC #14 – SUPPLY	No Asbestos Detected	AHU #3 – SUPPLY (LIBRARY)	No Asbestos Detected
		AHU #3 – RETURN (LIBRARY)	No Asbestos Detected
		AHU #R-1 - SUPPLY (AUDITORIUM)	No Asbestos Detected
		AHU #1 – RETURN (AUDITORIUM)	No Asbestos Detected

NYC-WTC_000213039