

Settled dust bulk sample chain of custody form and laboratory results

ATC ASSOCIATES INC.

BATCH NO.

20000

BULK SAMPLE DATA AND CHAIN OF CUSTODY FORM

PROJECT INFORMATION

1. Client: NYC - BOE	2. Project Name: AHERA REINSPECTION	3. Project # 14584-0864	4. Project Manager: ANDREAS ANDREOU
2a. Project Address: 90 Trinity Place, New York, NY 10006			4a. Investigator: Yiannis Efsthathiou
5. Date: 2/8/02	6. Building Name: M894	8. Turnaround Time: ☐ STAT ☐ 24 HRS ☐ 72 HRS ☐ OTHER ☐ 6 HRS ☐ 48 HOURS ☐ NORMAL	9. Comments (Field): Analyzed all them for fiberglass
7. Sampling Areas:		10. Time in / Time out:	

H.A.#	SAMPLE ID NUMBER	MATERIAL DESCRIPTION	LOCATION	FLOOR NUMBER	RESULTS
	M894-2/8/02- Fiberglass-01	Settled Dust	1st Floor Lobby (Floor)		
	M894-2/8/02- Fiberglass-02	Settled Dust	Cafeteria (Floor)		
	M894-2/8/02- Fiberglass-03	Settled Dust	13th Floor hallway (Floor)		
	M894-2/8/02- Fiberglass-04	Settled Dust	Classroom # 1106 (Floor)		
	M894-2/8/02- Fiberglass-05	Settled Dust	9th Floor hallway (Floor)		
	M894-2/8/02- Fiberglass-06	Settled Dust	7th Floor hallway (Floor)		
	M894-2/8/02- Fiberglass-07	Settled Dust	Classroom # 506 (Floor)		
	M894-2/8/02- Fiberglass-08	Settled Dust	5th Floor hallway (Floor)		
	M894-2/8/02- Fiberglass-09	Settled Dust	3rd Floor hallway (Floor)		

CHAIN OF CUSTODY

17. Relinquished By:	18. Date:	19. Time:	20. Received By:	21. Date:	22. Time:	23. Method of Submittal:
Yiannis Efsthathiou			E.A. CARTEROS	2/8/02	1740	FIELD
						WALK IN
						US MAIL
						FED-X
						OTHER

LAB INFORMATION

24. Name and Signature:	25. Date:	26. Time:	27. Comments (Lab):
24a. Analyzed By: E. A. CARTEROS	2/8/02	1740	9 PM
24b. Analyzed By:			
24c. QC By:			