



AIR MONITORING DATA AND

CHAIN OF CUSTODY FORM

Page 1 of 2

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other PCIS

PROJECT INFORMATION

1. Project Name <u>PS 234 M</u>	3. Project # <u>41584-0823</u>	4. Project Monitor: <u>MARK NAKHUMOVICH</u>	4c. Rotameter Number: <u>HP107</u>
2a. Project Address <u>242 Greenwich St, NY, NY 10007</u>	4b. Air Sampler: <u>MARK NAKHUMOVICH</u>		
5. Monitoring Location: <u>3-12 ENTIRE</u>	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacturer Lot #	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacturer Lot # <u>00262916</u>	9. Type: a. ☐ Background b. ☐ Pre-Abate
		c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA	f. ☐ Environmental g. ☒ Ambient h. ☐ Other

AIR SAMPLE RECORD

Sample ID Number	Pump Number	12. Sample Location		13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol (liters)	16. # Fibers/Fields minus Blank	17. Fiber Conc. f/c
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End Avg			
				Field Blank								
				Field Blank								
01				First Floor-hallway	7:10	11:10	240	8.0	8.0	8.0	1920	
02				Cafeteria	7:12	11:12	240	8.0	8.0	8.0	1920	
03				Gymnasium	7:14	11:14	240	8.0	8.0	8.0	1920	
04				Auditorium	7:16	11:16	240	8.0	8.0	8.0	1920	
05				North playground	7:18	11:18	240	8.0	8.0	8.0	1920	
06				West playground	7:20	11:20	240	8.0	8.0	8.0	1920	
07				Roof-South PART	7:22	11:22	240	8.0	8.0	8.0	1920	
08				First Floor-hallway	11:10	15:10	240	8.0	8.0	8.0	1920	
09				North playground	11:18	15:18	240	8.0	8.0	8.0	1920	
10				West playground	11:20	15:20	240	8.0	8.0	8.0	1920	
11				Roof-South PART	11:22	15:22	240	8.0	8.0	8.0	1920	
12				Classroom 211	15:02	19:02	240	8.0	8.0	8.0	1920	

IN OF CUSTODY

19. Received By: <u>Y. Efsthion</u>	20. Date: <u>03/14/2010</u>	21. Time: <u>20:00</u>
--	--------------------------------	---------------------------

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>TEC</u>	23. Date: <u>3/10</u>	24. Time: <u>23:40</u>
a. Analyzed By: <u>MMI</u>		
b. QC By:		
c. Lab Batch #: <u>7043</u>		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238513
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

NYC-WTC_000218133

NYC-WTC_000218133

CITY_21MC100_000465933



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 2

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other plus

ECT INFORMATION

1C-BCE	2. Project Name PS 234 M		3. Project #	4. Project Monitor: MARK NAKHUMOVICH		4c. Parameter Number: HP107
	2a. Project Address 292 Greenwich St, NY, NY 10007		K1584-C823	4b. Air Sampler: MARK NAKHUMOVICH		
512	G-Asbestos Location: ENTIRE	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:		c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other
		Cassette/Filter Manufacture _____ Lot # _____	Cassette/Filter Manufacture _____ Lot # _____	a. ☐ Background b. ☐ Pre-Abate		

AIR SAMPLE RECORD

[illegible]

N OF CUSTODY

Impressed By	19 Received By:	20 Date:	21. Time:
	<i>W. H. Jones</i>	<i>10/12/02</i>	

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	V. E. M.	23. Date:	24. Time:	25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By:	<i>[Signature]</i>	3/12	23:40	
b. QC By:				
c. Lab Exam #:	7043			

[illegible]

VFLSTATISTIK

NYC-WTC 000218134

CITY_21MC100_000465940