NYC-WTC_000218157

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

ATC ASSOCIATES INC.

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other RUSH

PROJECT INFORMATION

7076 17/20 79569-79588

1. Client:	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number:
NYC - BOE	PS 234 M	14584-823	Kevin	SD087
	2a. Project Address: 292 GREENWICH ST NY NY 10007	3a. Task #	4a. Air Sampler: Fitzpatrick	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☑ TEM (0.45 micron MCE)	9. Type:	
3-14-02	ENTIRE SCHOOL VARIOUS LOCATIONS	Cassette/Filter Manufacture: ____ Lot #: ____	Cassette/Filter Manufacture: MMI Lot #: 00263916	a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☑ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
01				Field Blank									
02				Field Blank									
03				OPEN BLANK.									
04				1ST FLOOR HALLWAY. NEXT TO STAIRWELL #1	7:01 AM	02 AM	241	8.0	8.0	8.0	1928		
05				WESTSIDE OF CAFETERIA 1ST FLOOR.	7:03 AM	03 AM	240	8.0	8.0	8.0	1920		
06				SOUTHSIDE OF GYM.	7:04 AM	05 AM	242	8.0	8.0	8.0	1936		
07				WESTSIDE OF AUDITORIUM 2ND FLOOR.	7:07 AM	07 AM	240	8.0	8.0	8.0	1920		
08				NORTHSIDE OF PLAYGROUND	7:09 AM	10 AM	241	8.0	8.0	8.0	1928		

CHAIN OF CUSTODY

	18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I	[signature]	[signature]	03/19/02	
II				
III				

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:	3/15	3:00
b. QC By:		
c. Lab Batch #: 7076		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: MARK TELGESEN

27. Result To: ____
Beeper/Phone #'s ____

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_000465982

NYC-WTC_000218158

NYC 9/11 Public Portal Document

VATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other RUSH

PROJECT INFORMATION

1. Client:	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number:
NYC - BOE	PS 234 M	14584-0823	Kevin	SD057
	2a. Project Address: 292 GREENWICH ST NY NY 10007	3a. Task #	4a. Air Sampler: FITZPATRICK	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☑ TEM (0.45 micron MCE)	9. Type:	
3-14-02	ENTIRE SCHOOL VARIOUS LOCATIONS	Cassette/Filter Manufacture: ____ Lot #: ____	Cassette/Filter Manufacture: ____ Lot #: ____	a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☑ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
09				SOUTHSIDE OF ROOF AREA.	7 11 AM	1 11	240	8.0	8.0	8.0	1920		
10				WESTSIDE OF PLAYGROUND AREA.	7 14 AM	11 15 AM	241	8.0	8.0	8.0	1928		
11				1ST FLOOR HALLWAY NEXT TO STAIRWELL #1	11 17 AM	3 17 pm	240	8.0	8.0	8.0	1920		
12				NORTHSIDE OF PLAYGROUND	11 19 AM	3 19 pm	240	8.0	8.0	8.0	1920		
13				WESTSIDE OF PLAYGROUND	11 21 AM	3 22 pm	241	8.0	8.0	8.0	1928		
14				SOUTHSIDE OF ROOF AREA.	11 25 AM	3 27 pm	242	8.0	8.0	8.0	1936		

CHAIN OF CUSTODY

	18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I	[signature]	[signature]	3/14/02	
II				
III				

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:	3/15 - 3/20	
b. QC By:		
c. Lab Batch #: 7076		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: MARK PETERSEN

27. Result To: ____
Beeper/Phone #'s ____

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_0004659B3

NYC-WTC_000218159

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other RUSH

PROJECT INFORMATION

1. Client:	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number:
NYC - BOE	PS 234 M	14584-0823	Kurin	30087
	2a. Project Address: 292 Greenwich ST NY NY 10007	3a. Task #	4a. Air Sampler: Fitzpatrick	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:
3-14-02	ENTIRE SCHOOL VARIOUS LOCATIONS	Cassette/Filter Manufacture: ____ Lot #: ____	Cassette/Filter Manufacture: ____ Lot #: ____	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☑ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
15				SOUTHSIDE of classroom 2ND FLOOR RM 223	3 36 pm	7 36 pm	240	8.0	8.0	8.0	1920		
16				SOUTHSIDE of classroom 219 2ND FLOOR	3 38 pm	7 38 pm	240	8.0	8.0	8.0	1920		
17				SOUTHSIDE of classroom 215 2ND FLOOR	3 40 pm	7 40 pm	240	8.0	8.0	8.0	1920		
18				EASTSIDE of classroom KINDERGARTEN RM 118	5 56 pm	9 57 pm	241	8.0	8.0	8.0	1928		
19				EASTSIDE of classroom KINDERGARTEN RM 116	5 59 pm	9 59 pm	240	8.0	8.0	8.0	1920		
20				EASTSIDE of classroom KINDERGARTEN RM 122	6 01 pm	10 03 pm	242	8.0	8.0	8.0	1936		

CHAIN OF CUSTODY

	18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I	[signature]	[signature]	03/14/02	
II				
III				

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:	3/15	3:00
b. QC By:		
c. Lab Batch #: 7076		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: MARK FERGESEN

27. Result To: ____
Beeper/Phone #'s ____

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_0004659B4