



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 2

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RTS

PROJECT INFORMATION

1. Project Name: PS 234M
 2a. Project Address: 243 Greenwich St, NY, NY 10007
 3. Project #: 41584-0823
 4. Project Monitor: MARK NAKHUMOVICH
 4c. Rotameter Number: HP107
 4e. Air Sampler: MARK NAKHUMOVICH
 5. Type: ☐ Background ☐ Pre-Abate ☐ Abatement ☐ Post-Abate ☐ OSHA
 6. ☐ PCM (0.3 micron MCE) ☒ TEM (0.45 micron MCE)
 7. ☐ PCM (0.3 micron MCE) ☒ TEM (0.45 micron MCE)
 8. ☐ PCM (0.3 micron MCE) ☒ TEM (0.45 micron MCE)
 9. ☐ Environmental ☒ Ambient ☐ Other

AIR SAMPLE RECORD

10. Sample Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. /cc
		12a. IWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
16				Field Blank									
17				Field Blank									
01				First Floor - hallway	6:30	10:30	240	8.0	8.0	8.0	1920		
02				Cafeteria	6:32	10:32	240	8.0	8.0	8.0	1920		
03				Gymnasium	6:34	10:34	240	8.0	8.0	8.0	1920		
04				Auditorium	6:36	10:36	240	8.0	8.0	8.0	1920		
05				North playground	6:38	10:38	240	8.0	8.0	8.0	1920		
06				West playground	6:40	10:40	240	8.0	8.0	8.0	1920		
07				South part - Roof	6:42	10:42	240	8.0	8.0	8.0	1920		
08				Classroom 211	6:44	10:44	240	8.0	8.0	8.0	1920		
09				Classroom 229	6:46	10:46	240	8.0	8.0	8.0	1920		
10				Classroom 220	6:48	10:48	240	8.0	8.0	8.0	1920		
11				Kindergarten	6:50	10:50	240	8.0	8.0	8.0	1920		
12				North playground	10:38	14:48	240	8.0	8.0	8.0	1920		

CHAIN OF CUSTODY

19. Received By:	20. Date:	21. Time:
<u>Y. Efsthion</u>	<u>3/4/02</u>	<u>16:00</u>

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>ATC-TEM</u>	23. Date:	24. Time:
a. Analyzed By: <u>R. Ruy</u>	<u>3/5/02</u>	<u>18:00</u>
b. QC By:		
c. Lab Name:	<u>63999</u>	

25. Microscope Make/Serial #

☐ Nikon Labphoto 238913
☐ Nikon Labphoto 238917
☐ Nikon Labphoto 239079

18. Signature:

Y. Efsthion

19. Name:

Y. Efsthion

20. Phone #:

(416) 772-1155

21. Signature:

22. Signature:

23. Name:

CITY_21MC100_002878330



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 2

TURNAROUND TIME

☐ 2 hrs ☐ 5 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other POST

PROJECT INFORMATION

1. Project Name <u>PS 234 M</u> 2a. Project Address <u>293 Greenwich St, NY, NY 10007</u>		3. Project # <u>4584-0823</u>		4. Project Monitor: <u>MARK NAKHUMOVICH</u>		4c. Rotameter Number: <u>HP107</u>	
		4b. Air Sampler: <u>MARK NAKHUMOVICH</u>		5. Type: a. ☐ Background d. ☐ Post-Abate b. ☐ Pre-Abate e. ☐ OSHA			
6. Abatement Location: <u>ENTIRE</u>		7. ☐ PCM (0.8 micron MCE) Cassette/Fiber Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Fiber Manufacture _____ Lot # _____		f. ☐ Environmental g. ☒ Ambient h. ☐ Other	

AIR SAMPLE RECORD

File ID number	Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/L
		12a. NYA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
18				Field Blank									
				Field Blank									
13				West playground	10:40	14:40	240	8.0	8.0	8.0	1920		
14				First floor hallway	10:30	14:30	240	8.0	8.0	8.0	1920		
15				Roof	10:42	14:42	240	8.0	8.0	8.0	1920		

CHAIN OF CUSTODY

Impressed By:	19. Received By:	20. Date:	21. Time:
	<u>TD</u>	<u>3/9/02</u>	<u>16:00</u>

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
<u>ATC-TEM</u>	<u>3/9/02</u>	<u>18:00</u>
a. Analyzed By:		
<u>DRJ</u>		
b. QC By:		
<u>6979</u>		

25. Microscope Make/Serial #
☐ Nikon Labophot 238813 ☐ Nikon Labophot 238817 ☐ Nikon Labophot 239079

26. Sample ID:	27. Sample ID:
<u>VEGETATION</u>	<u>Y. Efsthion</u>

28. Sample ID:

29. Sample ID:

CITY_21MC100_002878331