



DURING
SCHOOL

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

RUSH

Page 1 of 11

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs

☐ Standard
☒ Other (RUSH)

PROJECT INFORMATION

Client: NYC BOE	2. Project Name: PS 89M	3. Project #: 14584-0819	4. Project Monitor: Daniel Finkley	4c. Rotameter Number: HP125
Date: WED 1/30/02	2a. Project Address: 801 WARREN STREET	3a. Task #	4a. Air Sampler:	
6. Abatement Location: REAR PLAYGROUND, REAR HALLWAY ALL FLOORS	☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE) MULTIMETERS	9. Type:	c. ☐ Abatement
	Cassette/Filter Manufacture: Lot # 00263916		a. ☐ Background	d. ☐ Post-Abate
			b. ☐ Pre-Abate	e. ☐ OSHA
				f. ☐ Environmental
				g. ☒ Ambient
				h. ☐ Other

DAILY AIR SAMPLE RECORD

Sample I.D. Number	11. Pump Number	12. Sample Location AT BREATHING ZONE			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
017				Field Blank CLOSED									
01		in side		CAFE	8:35 AM	12:25 PM	230	80	80	80	1840		
02		↓		1ST FLOOR HALLWAY	8:40	12:40	230	80	80	80	1840		
03		out side		OUTSIDE CAFE	8:42	12:42	230	8.0	80	80	1840		
04		↓		PLAYGROUND NORTH	8:44	12:44	230	8.0	80	80	1840		
05		in side		PLAYGROUND SOUTH	8:45	12:05	230	8.0	80	80	1840		
06		↓		AUDITORIUM REAR CENTRAL OF WALKWAY	8:40	12:00	230	8.0	80	80	1840		
06		↓		GYM SOUTH ENTRANCE	8:40	12:00	230	8.0	80	80	1840		

CHAIN OF CUSTODY

8. Relinquished By: [Signature]	19. Received By: [Signature]	20. Date: 01/30/02	21. Time: 2:15
6. ATC Project Manager: Andreas Andreou	27. Result To: Andreas Andreou	Beeper/Phone #'s: 646-772-1153	

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: [Signature]	23. Date: 1/30	24. Time: 8:00	25. Microscope Make/Serial #:
a. Analyzed By: [Signature]			☐ Nikon Labophot 238913
b. QC By:			☐ Nikon Labophot 238917
c. Lab Batch #: 6577			☐ Nikon Labophot 239079
28. Comments:			Analysis Methodology:
			PCM - NIOSH 7400A
			TEM - AHERA

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY 1 (1/01)

DURING
SCHOOLAIR MONITORING DATA
AND

RUSH

Page 11 of 11

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

PROJECT INFORMATION

1. Project Name <u>NYC BOE</u>	2. Project Name <u>PS 89M</u>	3. Project # <u>14584-0819</u>	4. Project Monitor <u>Daniel Finkley</u>	4c. Rotameter Number <u>HP125</u>
2a. Project Address <u>801 WARREN STREET</u>	3a. Task # <u>00263916</u>	4a. Air Sampler <u>00263916</u>	4b. Type: a. ☐ Background b. ☐ Pre-Abate	4c. Abatement d. ☐ Post-Abate e. ☐ OSHA
5. Abatement Location: <u>ROOF PLAYGROUND: 1ST FL. HALLWAY</u> <u>ALL FLOORS</u>	6. ☒ PCM (0.8 micron MCE) Cassette/Filter Manufacture Lot #	7. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture Lot #	8. ☒ Multi-Metals Lot #	9. ☐ Environmental g. ☒ Ambient h. ☐ Other

AIR SAMPLE RECORD

AT BREATHING ZONE

AM. PM.

Sample ID Number	Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
18				Field Blank									
				Field Blank									
07				Roof Central location	8:30 AM	12:20	230	80	80	80	1840		
08				ON STAND									
09				1st Floor Hallway	12:10 PM	1600	230	80	80	80	1840		
010				Playground North	12:12 PM	1602	230	80	80	80	1840		
011				AT COLUMN NEXT TO BENCH	12:14 PM	1604	230	80	80	80	1840		
				Playground South	12:20 PM	1610	230	80	80	80	1840		
				AT COLUMN NEXT TO BENCH									
				Roof Central location									

CHAIN OF CUSTODY

19. Released By: <u>[Signature]</u>	19. Received By: <u>[Signature]</u>	20. Date: <u>01/30/02</u>	21. Time: <u>2:15</u>
--	--	------------------------------	--------------------------

22. Result To: <u>Andreas Andreou</u>	23. Beeper/Phone #'s: <u>646-772-1153</u>
--	--

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>TEC</u>	23. Date: <u>1/31</u>	24. Time: <u>8:00</u>	25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: <u>[Signature]</u>	b. QC By:	c. Lab Batch #: <u>6517</u>	Analysis Methodology: PCM - NIOSH 7400A <u>TEM - AHERA</u>
28. Comments:			

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

AFTER
SCHOOLAIR MONITORING DATA
AND

RUSH

CHAIN OF CUSTODY FORM

Page

III

of

III

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

PROJECT INFORMATION

NYC BOE

WED
30/02
 2. Project Name PS 89M
 2a. Project Address 801 WARREN STREET

 3. Project # 14584-
 3a. Task # -0817

 4. Project Monitor: Danrel Finkley
 4a. Air Sampler: Danrel Finkley

 4c. Rotameter Number: 11P125

 6. Abatement Location: ROOF
PLAYGROUND: 1ST FL. HALLWAY
ALL FLOORS

 7. ☐ PCM (0.8 micron MCE)
 Cassette/Filter Manufacture
 Lot #

 8. ☒ TEM (0.45 micron MCE) MULTI-METAS
 Cassette/Filter Manufacture LOT # 916
 Lot # *00263916

5. Type:

 a. ☐ Background
 b. ☐ Pre-Abate

 c. ☐ Abatement
 d. ☐ Post-Abate
 e. ☐ OSHA

 f. ☐ Environmental
 g. ☒ Ambient
 h. ☐ Other

AIR SAMPLE RECORD

Sample ID Number	Pump Number	12. Sample Location <u>AT BREATHING ZONE</u>			13. Time (24 hrs clock) <u>P.M.</u>			14. Flow Rate (L/min)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
19.				Field Blank <u>OPEN.</u>									
				Field Blank									
012		<u>1st Side</u>		<u>CLASS RM 532 NORTH</u>	<u>3:13 PM</u>	<u>7:03 PM</u>	<u>230</u>	<u>8.0</u>	<u>8.0</u>	<u>80</u>	<u>1840</u>		
				<u>VENT UNIT</u>									
013				<u>CLASS RM 510 EAST</u>	<u>3:30 PM</u>	<u>7:20 PM</u>	<u>230</u>	<u>8.0</u>	<u>8.0</u>	<u>80</u>	<u>1840</u>		
				<u>VENT UNIT</u>									
014				<u>CLASS RM 202 SOUTH</u>	<u>3:37 PM</u>	<u>7:27 PM</u>	<u>230</u>	<u>8.0</u>	<u>8.0</u>	<u>80</u>	<u>1840</u>		
				<u>VENT UNIT</u>									
015				<u>2ND FLOOR SOUTH END</u>	<u>3:10 PM</u>	<u>7:00 PM</u>	<u>230</u>	<u>8.0</u>	<u>8.0</u>	<u>80</u>	<u>1840</u>		
				<u>TOP OF PLATFORM</u>									
016				<u>4TH FLOOR SOUTH END</u>	<u>3:15 PM</u>	<u>7:05 PM</u>	<u>230</u>	<u>8.0</u>	<u>8.0</u>	<u>80</u>	<u>1840</u>		
				<u>TOP OF PLATFORM</u>									

CHAIN OF CUSTODY

 Relinquished By: Finkley
 19. Received By: Andreou
 20. Date: 01/30/02 21. Time: 2:15
ATC Project Manager: Andreas Andreou
 27. Result To: Andreas Andreou
 Beeper/Phone #'s 646-772-1153

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

 22. Lab Name: VEA
 a. Analyzed By: WJH
 b. QC By: WJH
 c. Lab Batch #: G517

 23. Date: 1/31 24. Time: 8:00
 25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology

☐ PCM - NIOSH 7400A
☒ TEM - AHERA
28. Comments: 014 = CLASS RM 202