

ATC ASSOCIATES, INC.
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 03-01-02
CLIENT: NYC BOE
PROJECT ADDRESS: 210 Warren St.
New York, NY 10007
PROJECT NO: 41617-0562
SAMPLED BY: M. Nakhumovich
SAMPLE DATE: 03-01-02
DATE RECEIVED: 03-01-02
DATE ANALYZED: 03-01-02
SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION (µg/ft²)	DETECTION LIMIT (µg/ft²)
01	9699	Outside the Room 226 Corridor in Front of the Door	11.2	9.0
02	9699	Floor in Front of Window to North Side Room 226 Floor	<9.0	9.0
03	9699	Floor in Front of Window to West Side Room 226 Floor	<9.0	9.0
04	9699	Window Sills West Side Window Room 226	<16.0	16.0
44	9699	Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg

NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 µg/ft², Window sills 250 µg/ft²,
Window wells 400 µg/ft², Exterior surfaces 800 µg/ft².

NOTE 3:
Blank units are in µg

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

BCU

REPORT PREPARED BY: _____

[Signature]

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

[Signature]

LABORATORY DIRECTOR: _____

[Signature]

ATC Environmental Inc. (ATC) is accredited by the New York State Department of Health Environmental Laboratory Approval Program (NYS DOH ELAP) to perform analysis of lead in paint and dust wipes (ELAP #10879).

ATC ASSOCIATES INC.
DUST WIPE SAMPLING - CHAIN OF CUSTODY
 104 EAST 25TH STREET, 10TH FLOOR
 NEW YORK, NEW YORK 10010

PHONE: 212-353-8280 FAX: 212-353-8306

PAGE 1 OF 1

TOTAL # OF SAMPLES: _____

Client Name: New York City Board of Education

Project Number: 41617-0562

Date: 3/1/02

Project Address: 201 Warren St. NY, NY 10007

Project Manager: A. Andreou

Turnaround
Time: Rush

Investigator: MARK NAKHUMOVICH

Building Type: School

Analysis
Required: Lead in dust

Sample ID#	Room, Component, Location	Surface Condition	Dimension of sample area (in. x in.)	Detection Limit	Result (µg/ft²)
01	Outside the Room 226 - corridor - - in front of the door (floor)	☐ Visible Dust ☐ Visible Debris ☒ No Visible Dust or Debris	12" x 12"	9.0	11.2
02	Floor in front of window to North side - Room 226 (floor)	☐ Visible Dust ☐ Visible Debris ☒ No Visible Dust or Debris	12" x 12"	9.0	< 9.0
03	Floor in front of window to West side Room 226 (floor)	☐ Visible Dust ☐ Visible Debris ☒ No Visible Dust or Debris	12" x 12"	9.0	< 9.0
04	Window sills - West side window Room 226	☐ Visible Dust ☐ Visible Debris ☒ No Visible Dust or Debris	9" x 9"	16.0	< 16.0
05	BLANK	☐ Visible Dust ☐ Visible Debris ☐ No Visible Dust or Debris		9.0	< 9.0

COMMENTS: Please
page

(ADDITIONAL COMMENTS
ON BACK)

RELINQUISHED BY (SIGNATURE BELOW):	DATE/TIME	RECEIVED BY (SIGNATURE BELOW):	DATE/TIME	LABORATORY:
		<u>A. Andreou</u>	<u>03/01/2002</u>	
PRINT NAME:		PRINT NAME:		NULL#
				FLAP#

CITY_21MC100_002880182