



AIR MONITORING DATA AND

CHAIN OF CUSTODY FORM

Page 1 of 1

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other RUSH

PROJECT INFORMATION

1. Client: NMC-BOE 2. Project Name: H.S. OF ECONOMICS, Finance 3. Project #: 4584-865 4. Project Monitor: Kevin Fitzpatrick 4c. Rotameter Number: SD087

2a. Project Address: 100 TRINITY PLACENY NY 3a. Task #: 00001 4a. Air Sampler: Fitzpatrick

5. Date: 3-29-02 6. Abatement Location: ENTIRE SCHOOL VARIOUS LOCATIONS 7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____ 8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture _____ Lot # 98116617 9. Type: ☐ Background ☐ Post-Abate ☐ Pre-Abate ☐ Abatement ☐ OSHA ☒ Environmental ☒ Ambient ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
<u>01</u>				Field Blank									
<u>02</u>				Field Blank									
<u>03</u>				<u>open BLANK</u>									
<u>04</u>				<u>OUTSIDE MAIN ENTRANCE of school SIDEWALK SOUTHSIDE</u>	<u>6:50 AM</u>	<u>10:50 AM</u>	<u>240</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1920</u>		
<u>05</u>				<u>OUTSIDE OF AUDITORIUM in main LOBBY 1ST FLOOR</u>	<u>6:52 AM</u>	<u>10:52 AM</u>	<u>240</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1920</u>		
<u>06</u>				<u>NORTHSIDE OF AUDITORIUM 1ST FLOOR.</u>	<u>6:54 AM</u>	<u>10:54 AM</u>	<u>240</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1920</u>		
<u>07</u>				<u>SOUTHSIDE OF ROOF AREA.</u>	<u>6:56 AM</u>	<u>10:57 AM</u>	<u>241</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1928</u>		
<u>08</u>				<u>7TH FLOOR STAIRWELL B. SOUTHSIDE</u>	<u>6:59 AM</u>	<u>10:59 AM</u>	<u>240</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1920</u>		

CHAIN OF CUSTODY

18. Relinquished By: Kevin Fitzpatrick 19. Received By: _____ 20. Date: _____ 21. Time: _____

I Kevin Fitzpatrick
 II _____
 III _____

26. ATC Project Manager: MARK TERSESEN 27. Result To: _____
 Beeper/Phone #'s _____

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: HFCOPECU 23. Date: 3/30 24. Time: 11:00

a. Analyzed By: WCB
 b. QC By: _____
 c. Lab Batch #: _____

25. Microscope Make/Serial #: _____
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
 PCM - NIOSH 7400A
TEM - AHERA

28. Comments: _____

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_002881720



7265 AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 2

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other PUSH

PROJECT INFORMATION

1. Client: <u>NYC-BOE</u>	2. Project Name: <u>HS OF ECONOMICS + FINANCE</u>	3. Project #: <u>1584-865</u>	4. Project Monitor: <u>Kevin</u>	4c. Rotameter Number: <u>50087</u>
	2a. Project Address: <u>100 TRINITY PLACE NYM</u>	3a. Task #: <u>80001</u>	4a. Air Sampler: <u>Fitzpatrick</u>	
5. Date: <u>3-29-02</u>	6. Abatement Location: <u>ENTIRE SCHOOL VARIOUS LOCATIONS</u>	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture _____ Lot # <u>98116617</u>	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location	13. Time (24 hrs clock)	14. Flow Rate (L/min.)	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA 12b. OWA	13a. Start 13b. End 13c. Total	14a. Start 14b. End 14c. Avg			
			Field Blank				
			Field Blank				
09			NORTHSIDE OF 8 TH FL CAFETERIA	7:01 AM 11:02 AM	241	8.0 8.0 8.0	1928
10			NEXT TO Rm 920 IN HALLWAY	7:03 AM 11:05 AM	242	8.0 8.0 8.0	1936
11			SOUTHSIDE OF CLASSROOM 801 8 TH FLOOR	7:04 AM 11:04 AM	240	8.0 8.0 8.0	1920
12			NEXT TO CLASSROOM 703 7 TH FLOOR. HALLWAY.	7:13 AM 11:14 AM	241	8.0 8.0 8.0	1928
13			EASTSIDE OF CLASSROOM 604 6 TH FLOOR.	7:16 AM 11:16 AM	240	8.0 8.0 8.0	1920
14			NEXT TO MENS ROOM 502 HALLWAY.	7:21 AM 11:21 AM	240	8.0 8.0 8.0	1920

CHAIN OF CUSTODY

18. Relinquished By: <u>[Signature]</u>	19. Received By:	20. Date:	21. Time:

26. ATC Project Manager: <u>MARK TORPESSEN</u>	27. Result To: _____ Beeper/Phone #'s _____
---	--

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>ATC ELAP</u>	23. Date: <u>3/29/02</u>	24. Time: <u>11:00</u>	25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: <u>[Signature]</u>			
b. QC By:			
c. Lab Batch #:			
28. Comments:			Analysis Methodology PCM - NIOSH 7400A <u>TEM - AHERA</u>

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_002881721



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 3 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other PUSH

PROJECT INFORMATION

1. Client: NYC- BOE		2. Project Name: H.S OF ENVIRONMENTAL FINANCE		3. Project #: 1584-865		4. Project Monitor: Kevin		4c. Rotameter Number: 50087	
		2a. Project Address: 100 TRINITY PLACE NY		3a. Task #: 00001		4a. Air Sampler: FITZPATRICK			
5. Date: 3-29-02		6. Abatement Location: ENTIRE SCHOOL VARIOUS LOCATIONS		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture _____ Lot # 981166A		9. Type: a. ☐ Background d. ☐ Abatement b. ☐ Pre-Abate e. ☐ OSHA	
								f. ☐ Environmental g. ☒ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
				Field Blank									
				Field Blank									
15				EAST SIDE OF CLASSROOM 405 4 TH FLOOR	7:24 AM	11:26 AM	242	8.0	8.0	8.0	1936		
16				NEXT TO MENS ROOM 302 - 3 RD FLOOR	7:27 AM	11:30 AM	243	8.0	8.0	8.0	1944		
17				OUTSIDE OF MAIN ENTRANCE of school SIDEWALK SOUTHSIDE	11:33 AM	2:33 PM	240	8.0	8.0	8.0	1920		
18				OUTSIDE OF AUDITORIUM LOBBY AREA 1 ST FLOOR	1:36 AM	3:37 PM	241	8.0	8.0	8.0	1928		
19				NEXT TO STAIRCASE B. 7 TH FLOOR. SOUTHSIDE	1:39 AM	3:39 PM	240	8.0	8.0	8.0	1920		
20				SOUTHSIDE OF ROOF AREA	1:40 AM	3:42 PM	242	8.0	8.0	8.0	1936		

CHAIN OF CUSTODY

18. Relinquished By: <i>[Signature]</i>	19. Received By: <i>H. E. [Signature]</i>	20. Date: 3/29/02	21. Time: 20:00
26. ATC Project Manager: MARK TERPESSEN			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: NYC DEPT	23. Date: 3/29/02	24. Time: 1:00	25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079 Analysis Methodology PCM - NIOSH 7400A TEM - AHERA
a. Analyzed By: <i>[Signature]</i>			
b. QC By:			
c. Lab Batch #: 7265			
28. Comments:			

27. Result To: _____
Beeper/Phone #'s: _____

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)