



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 1

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other PUSA

PROJECT INFORMATION

1. Client: NYC-BOE		2. Project Name: HSE ECONOMICS + Finance		3. Project #: 14580-865		4. Project Monitor: Kevin	
		2a. Project Address: 100 TRINITY PLACE NY NY		3a. Task #: 80001		4a. Air Sampler: Fitzpatrick	
5. Date: 3-31-02		6. Abatement Location: ENTIRE SCHOOL VARIOUS LOCATIONS		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture _____ Lot # 98116617	
				9. Type: a. ☐ Background b. ☐ Pre-Abate		c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA	
						f. ☐ Environmental g. ☒ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
01				Field Blank									
02				Field Blank									
03				open BLANK.									
04				OUTSIDE MAIN ENTRANCE NORTHSIDE OF SIDEWALK.	7:00 AM	11:00 AM	240	8.0	8.0	8.0	1920		
05				OUTSIDE OF AUDITORIUM 1ST FLOOR LOBBY AREA.	7:02 AM	11:02 AM	240	8.0	8.0	8.0	1920		
06				7TH FLOOR STAIRWELL "B" SOUTHSIDE	7:04 AM	11:04 AM	240	8.0	8.0	8.0	1920		
07				EASTSIDE OF ROOF AREA.	7:06 AM	11:06 AM	240	8.0	8.0	8.0	1920		
08				SOUTHSIDE OF AUDITORIUM 1ST FLOOR.	7:09 AM	11:10 AM	241	8.0	8.0	8.0	1928		

CHAIN OF CUSTODY

18. Relinquished By: [Signature]	19. Received By: [Signature]	20. Date: 3/31/02	21. Time: 4 PM

26. ATC Project Manager: MARK TERSEN	27. Result To: _____ Beeper/Phone #'s _____
--	--

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: [Signature]	23. Date: 3/31/02	24. Time: 18:00	25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: [Signature]			Analysis Methodology: PCM - NIOSH 7400A TEM - AHERA
b. QC By:			
c. Lab Batch #:			
28. Comments:			

WHITE - File

YELLOW - Client/Report

PINK - Lab

GREEN - [unclear]

CITY_21MC100_002881764



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

 Page 2 of 2

TURNAROUND TIME				
☐ 2 hrs	☐ 6 hrs	☐ 48 hrs	☐ Standard	
☐ 4 hrs	☐ 24 hrs	☐ 72 hrs	☐ Other <u>PUSH</u>	

PROJECT INFORMATION

1. Client: NYC- BOE		2. Project Name: H.S. COMMUNITY CENTER		3. Project #: 4584-865		4. Project Monitor: Kevin Fitzpatrick	
		2a. Project Address: 100 TRINITY PLACE NY		3a. Task #: 00001		4c. Rotameter Number: 30087	
5. Date: 3-31-02	6. Abatement Location: ENTIRE SCHOOL VARIOUS LOCATIONS	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture _____ Lot # 98116617		9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA	
						f. ☐ Environmental g. ☒ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
09				9 TH FLOOR HALLWAY OUTSIDE OF MENS ROOM	7:11 AM	11:12 AM	241	8.0	8.0	8.0	1928		
10				8 TH FLOOR TEACHERS LOUNGE RM 801	7:14 AM	11:16 AM	242	8.0	8.0	8.0	1936		
11				7 TH FLOOR HALLWAY NEXT TO ROOM 703	7:17 AM	11:17 AM	240	8.0	8.0	8.0	1920		
12				6 TH FLOOR WESTSIDE OF CLASSROOM 604	7:21 AM	11:21 AM	240	8.0	8.0	8.0	1920		
13				5 TH FLOOR HALLWAY NEXT TO CLASSROOM 503	7:24 AM	11:25 AM	241	8.0	8.0	8.0	1920		
14				4 TH FLOOR CLASSROOM 405 SOUTH SIDE	7:27 AM	11:27 AM	240	8.0	8.0	8.0	1920		

CHAIN OF CUSTODY

18. Relinquished By: Kevin Fitzpatrick	19. Received By: Mark Ferguson	20. Date: 3.31.02	21. Time: 4PM
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC ELAP	23. Date: 3/31/02	24. Time: 18:00	25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: WJH			
b. QC By:			
c. Lab Batch #:			Analysis Methodology PCM - NIOSH 7400A <u>TEM - AHERA</u>
28. Comments:			

26. ATC Project Manager: MARK FERGUSON	27. Result To: Beeper/Phone #'s _____
--	--

CITY_21MC100_002881765



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

 Page 3 of 3
TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other REST
PROJECT INFORMATION

1. Client: NYC- BOE		2. Project Name: H.S ECONIMICST FINANCE		3. Project #: 14584-865		4. Project Monitor: Kelin Fitzpatrick		4c. Rotameter Number: 50087	
		2a. Project Address: 100 TRINITY PLACE		3a. Task #: 00001		4a. Air Sampler: FITZPATRICK			
5. Date: 3-31-02		6. Abatement Location: ENTIRE SCHOOL VARIOUS LOCATIONS		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacturer: _____ Lot #: _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacturer: _____ Lot #: 9811667		9. Type: a. ☐ Background d. ☐ Post-Abate b. ☐ Pre-Abate e. ☐ OSHA	
								f. ☐ Environmental g. ☒ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
				Field Blank									
				Field Blank									
15				3 RD FLOOR HALLWAY OUTSIDE OF CLASSROOM 303	7:31 AM	11:32 AM	241	8.0	8.0	8.0	1928		
16				SOUTHSIDE OF CAFETERIA 8 TH FLOOR	7:35 AM	11:35 AM	240	8.0	8.0	8.0	1920		
17				OUTSIDE OF MAIN ENTRANCE NORTHSIDE OF STAIRWELL	11:42 AM	3:42 PM	240	8.0	8.0	8.0	1920		
18				OUTSIDE OF AUDITORIUM 1 ST FLOOR LOBBY AREA	11:44 AM	3:46 PM	242	8.0	8.0	8.0	1936		
19				7 TH FLOOR STAIRWELL SOUTHSIDE	11:46 AM	3:47 PM	241	8.0	8.0	8.0	1928		
20				EASTSIDE OF ROOF AREA	11:48 AM	3:49 PM	241	8.0	8.0	8.0	1928		

CHAIN OF CUSTODY

18. Relinquished By: [Signature]	19. Received By: NI	20. Date: 3/31/02	21. Time: 4 PM
II			
III			

26. ATC Project Manager: MARK TERPESSEN	27. Result To: _____ Beeper/Phone #'s: _____
---	---

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:	25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By:			
b. QC By:			
c. Lab Batch #:			Analysis Methodology PCM - NIOSH 7400A TEM - AHERA
28. Comments:			

CITY_21MC100_002881766