

ATC ASSOCIATES, INC.

Page 1 of 10

TIME 11:05 AM

INDOOR AIR QUALITY FIELD REPORT

(933 M)

LOCATION H.S. FOR ECONOMICS & FINANCE DATE 5/2/02 PROJECT NO. 19/25-0291

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (µg/m³)	TVOCs (ppm)
MAIN ENTRANCE		59.8	50.4	438	2	38	0.0
NORTH OF MAIN ENTRANCE		59.7	51.9	436	2	48	0.0
SOUTH OF MAIN ENTRANCE		~~61.3~~ 61.3	47.6	450	2	41	0.0
LOBBY 1ST FLOOR	4	63.5	54.4	539	1	15	0.0
AUDITORIUM	12	66.2	56.7	571	0	7	0.0
Elevator Lobby 1st Floor	2	68.4	56.2	567	0	13	0.0
10th Floor Hallway		72.3	56.1	1014	0	14	0.0
Room #1002		72.1	52.1	837	0	26	0.0
Room #1006	4	72.3	49.7	845	0	21	0.0
Hallway outside #1006	1	72.9	48.5	835	0	16	0.0
Guideline levels ASHRAE/AIHA/EPA		68 - 75°F/winter 73 - 79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 µg/m³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: Rud Dodgins Date: 5/2/02

CITY_21MC100_002882070

ATC ASSOCIATES, INC.

Page 2 of 10TIME 11:20 AM

INDOOR AIR QUALITY FIELD REPORT

(933 M)

LOCATION H.S. FOR ECONOMICS & FINANCE DATE 5/2/02 PROJECT NO. 19125-0291

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (µg/m³)	TVOCs (ppm)
STAIR 'A' TO 9th floor		72.3	47.6	764	0	24	0.0
Hallway outside #915		72.7	48.0	919	1	23	0.0
Room #915	5	72.9	48.1	950	0	30	0.0
Room #911	1	73.0	48.2	972	1	27	0.0
Room #913	2	73.2	48.5	994	0	25	0.0
Room #910	1	73.4	48.5	1088	1	24	0.0
Room #909	1	73.4	48.2	1216	1	35	0.0
Room #906	1	73.9	46.5	1082	1	21	0.0
Room #905		73.8	46.0	1054	1	20	0.0
Room #904	3	74.2	44.5	960	1	17	0.0
Guideline levels ASHRAE/AIHA/EPA		68-75°F/winter 73-79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 µg/m³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: Rud Daddagun Date: 5/2/02

CITY_21MC100_002882071

ATC ASSOCIATES, INC.

Page 3 of 10

TIME 11:25 AM

INDOOR AIR QUALITY FIELD REPORT

(933M)

LOCATION H.S. FOR ECONOMICS & FINANCE

DATE 5/2/02

PROJECT NO. 19125-0291

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (µg/m³)	TVOCs (ppm)
Room # 933	3	74.8	45.3	931	1	42	0.0
STAIR A TO 8th floor	1	74.3	46.0	1140	1	24	0.0
CAFETERIA	21	72.9	44.4	965	1	18	0.0
CAFETERIA CENTER	14	71.8	44.2	884	1	16	0.0
CAFETERIA SERVING AREA		71.9	44.1	859	1	17	0.0
KITCHEN		73.6	43.1	1140	1	15	0.0
Hallway/Elev CAFETERIA	FULL	71.9	44.9	915	1	95	0.0
STAIR A TO 8th floor	FULL	74.3	52.6	2040	0	23	0.0
Room # 706	5	75.4	49.9	1340	0	12	0.0
Room # 705	13	75.6	50.2	1368	1	10	0.0
Guideline levels ASHRAE/AIHA/EPA		68 - 75°F/winter 73 - 79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 µg/m³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: [Signature] Date: 5/2/02

CITY_21MC100_002882072

ATC ASSOCIATES, INC.

Page 4 of 10

TIME 11:38 AM

INDOOR AIR QUALITY FIELD REPORT

(933M)

LOCATION H.S. FOR ECONOMICS & FINANCE DATE 5/2/02 PROJECT NO. 19/25-0291

Location	Occup.	Temperature (F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates ($\mu\text{g}/\text{m}^3$)	TVOCs (ppm)
Room #703		75.2	46.1	897	1	16	0.0
Room #702A	1	74.6	42.7	769	1	8	0.0
Hallway 7th Elev Area		74.8	43.6	835	1	25	0.0
STAIR A TO 6 FL	4	74.8	44.9	1219	1	26	0.0
Room #608	27	75.4	47.0	1123	1	19	0.0
Room #607	10	74.8	44.2	829	1	12	0.0
Hallway OUTSIDE #606		74.5	44.7	832	1	11	0.0
Room #605	3	74.8	44.1	780	1	6	0.0
Room #604	1	74.9	44.4	842	1	8	0.0
Hallway OUTSIDE 604	1	74.8	45.2	848	1	8	0.0
Guideline levels ASHRAE/AIHA/EPA		68-75°F/winter 73-79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 $\mu\text{g}/\text{m}^3$ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: [Signature]Date: 5/2/02

ATC ASSOCIATES, INC.

Page 5 of 10

TIME 12:48

INDOOR AIR QUALITY FIELD REPORT

(933M)

LOCATION H.S. FOR ECONOMICS & FINANCE

DATE 5/2/02

PROJECT NO. 19125-0291

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (µg/m³)	TVOCs (ppm)
Room # 510	1	75.3	45.7	977	1	19	0.0
Room # 507	22	75.5	46.0	1050	1	17	0.0
Room # 509	15	75.4	46.3	1025	1	10	0.0
Room # 410	19	75.8	46.3	1290	1	41	0.0
Room # 305	28	76.6	47.3	1025	1	6	0.0
Room # 204	20	75.7	43.1	795	1	11	0.0
BASEMENT Gym	8	74.9	44.4	692	1	12	0.0
MAIN ENTRANCE		59.0	45.0	447	3	48	0.0
NORTH OF ENTRANCE		58.9	45.2	463	3	52	0.0
SOUTH OF ENTRANCE		59.1	46.8	440	3	48	0.0
Guideline levels ASHRAE/AIHA/EPA		68-75°F/winter 73-79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 µg/m³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: R. D. Dillman Date: 5/2/02

CITY_21MC100_002882074

ATC ASSOCIATES, INC.

Page 6 of 10

TIME 1:35 PM

INDOOR AIR QUALITY FIELD REPORT

(933M)

LOCATION H.S. FOR ECONOMICS & FINANCE

DATE 5/2/02

PROJECT NO. 19125-0291

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (µg/m³)	TVOCs (ppm)
MAIN ENTRANCE		61.0	58.7	448	~~448~~ 2	79	0.0
NORTH OF ENTRANCE		61.8	58.9	447	2	81	0.0
SOUTH OF ENTRANCE		61.3	64.6	426	2	76	0.0
1ST FLOOR LOBBY	5	68.4	65.5	686	1	19	0.0
AUDITORIUM	3	68.3	65.3	598	1	14	0.0
10th Floor Hallway		71.2	60.4	746	0	19	0.0
Room #1002	1	71.9	59.3	710	0	20	0.0
Room #1006	2	72.8	56.7	636	0	12	0.0
OUTSIDE Room #1006 - Hallway	1	73.5	56.9	604	0	12	0.0
STAIR #1 TO 9th Floor.		73.2	55.5	735	0	14	0.0
Guideline levels ASHRAE/AIHA/EPA		68-75°F/winter 73-79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 µg/m³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: [Signature] Date: 5/2/02

CITY_21MC100_002882075

TIME 1:50 PMATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORTPage 7 of 10LOCATION H.S. FOR ECONOMICS & FINANCE (933M) DATE 5/2/02 PROJECT NO. 19125-0291

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (µg/m³)	TVOCs (ppm)
Room # 915	5	73.5	57.0	1246	0	52	0.0
Room # 910	3	74.4	56.6	1284	0	27	0.0
Room # 909	1	74.3	55.7	1219	0	29	0.0
OUTSIDE Room # 907		74.4	54.3	1285	0	32	0.0
Room # 905		74.7	52.4	1078	0	18	0.0
Room # 906	1	74.5	51.5	874	1	17	0.0
Room # 904	2	74.8	50.1	825	1	14	0.0
Elevator Area 9FL	2	74.9	49.8	925	1	20	0.0
Hallway outside # 915		75.4	50.0	862	1	34	0.0
STAIR 'A' TO 8 FLOOR		75.2	49.7	898	1	23	0.0
Guideline levels ASHRAE/AIHA/EPA		68 - 75°F/winter 73 - 79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 µg/m³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: [Signature] Date: 5/2/02

ATC ASSOCIATES, INC.

Page 8 of 10

TIME 1: 55 PM

INDOOR AIR QUALITY FIELD REPORT

(933 M)

LOCATION H.S. FOR ECONOMICS & FINANCE DATE 5/2/02 PROJECT NO. 19/25-0291

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (µg/m³)	TVOCs (ppm)
CAFETERIA NORTH		73.8	52.4	750	1	36	0.0
CAFETERIA SOUTH		73.6	52.1	773	1	38	0.0
CAFETERIA CENTER		73.5	52.6	727	1	35	0.0
KITCHEN	1	73.9	53.0	690	1	22	0.0
SERVING AREA		73.1	52.7	684	1	31	0.0
STAIR 'A' 7th floor		73.7	52.9	691	1	30	0.0
Room # 705	25	74.3	51.2	810	1	15	0.0
Room # 703	35	75.6	53.0	908	1	15	0.0
Hallway outside 702	20	75.5	49.8	823	1	15	0.0
Elevator Area	10	75.2	49.1	739	1	13	0.0
Guideline levels ASHRAE/AIHA/EPA		68 - 75°F/winter 73 - 79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 µg/m³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: [Signature] Date: 5/2/02

ATC ASSOCIATES, INC.

Page 9 of 10

TIME 2:10 PM

INDOOR AIR QUALITY FIELD REPORT

(933M)

LOCATION H.S. FOR ECONOMICS & FINANCE

DATE 5/2/02

PROJECT NO. 19/25-0291

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (µg/m³)	TVOCs (ppm)
STAIR 'A' TO 6th Fl	FULL	75.5	51.0	1245	1	23	0.0
Room # 608	10	76.4	50.9	917	1	14	0.0
Room # 606	15	76.4	51.9	963	1	17	0.0
Room # 607	8	75.3	49.0	793	1	13	0.0
Room # 604	8	75.0	48.6	678	1	21	0.0
Room # 605	18	75.0	49.4	792	1	18	0.0
Hallway outside 604	2	75.4	49.5	756	1	21	0.0
STAIR 'A' 5th Floor	3	76.1	51.4	768	1	36	0.0
Room # 509	20	76.0	50.7	1080	1	20	0.0
Room # 510	17	76.1	50.0	1016	1	19	0.0
Guideline levels ASHRAE/AIHA/EPA		68 -75°F/winter 73 -79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 µg/m³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: [Signature] Date: 5/2/02

CITY_21MC100_002882078

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 10 of 10

TIME 2:25 PM

(933 M)

LOCATION H.S. FOR ECONOMICS & FINANCE

DATE 5/2/02

PROJECT NO. 19125-0291

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (µg/m³)	TVOCs (ppm)
Room #507	15	75.7	48.1	819	1	30	0.0
Room #407	13	76.1	49.3	877	1	58	0.0
Room #408	24	76.2	50.2	983	1	29	0.0
Room #309	20	76.7	49.7	916	1	24	0.0
Room #307	16	77.0	49.6	958	1	24	0.0
Room #203	15	76.4	47.1	702	1	14	0.0
Gym	20	75.6	50.2	960	1	17	
MAIN ENTRANCE		67.1	47.6	486	1	128	0.0
NORTH OF MAIN ENTRANCE		66.8	45.2	472	3	134	0.0
SOUTH OF MAIN ENTRANCE		66.2	61.9	462	3	132	0.0
Guideline levels ASHRAE/AIHA/EPA		68 - 75°F/winter 73 - 79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 µg/m³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: [Signature]

Date: 5/2/02