

Polarized Light Microscopy (PLM) Results, EPA/600/R-93/116 (NYS ELAP 198.1) Point Count Method
RJ Lee Group Project No. LSH204785

Analyst: WHP

Analysis Report for Gash Emergency Samples collected 06/05/02

Sample ID	RJ Lee Group Sample ID	Building/location (desc.)	Non-Asbestos Components	Asbestos Content	Comments
8-G (2 bags received) 130 Liberty Street	3030851	Floor 8 Grid G	Non-fibrous mat'l Fibrous Glass Cellulose	60.50 % 34.75 % 4.25 %	Chrysotile 0.5% White Fibrous Debris
9-G (Bag) 130 Liberty Street	3030852	Floor 9 Grid G	Non-fibrous mat'l Fibrous Glass Cellulose	63.25 % 27.50 % 8.50 %	Chrysotile 0.75% White Fibrous Debris
10-D (Bag) 130 Liberty Street	3030853	Floor 10 Grid D	Non-fibrous mat'l Fibrous Glass Cellulose	59.00 % 37.25 % 3.75 %	None detected White Fibrous Debris
11-B (3 bags received) 130 Liberty Street	3030854	Floor 11 Grid B	Non-fibrous mat'l Fibrous Glass Cellulose	73.50 % 20.00 % 6.50 %	Amosite < 0.25% Gray Fibrous Debris
12-D (Bag) 130 Liberty Street	3030857	Floor 12 Grid D	Non-fibrous mat'l Fibrous Glass Cellulose	55.75 % 36.25 % 6.75 %	Chrysotile 1.25% White Fibrous Debris
15-A (Bag) 130 Liberty Street	3030863	Floor 15 Grid A	Non-fibrous mat'l Fibrous Glass Cellulose	68.00 % 25.75 % 6.25 %	None detected Gray Fibrous Debris
17-C (Bag) 130 Liberty Street	3030859	Floor 17 Grid C	Non-fibrous mat'l Cellulose Fibrous Glass	67.25 % 22.50 % 10.25 %	None detected White Fibrous Debris
17-F (Bag) 130 Liberty Street	3030860	Floor 17 Grid F	Non-fibrous mat'l Fibrous Glass Cellulose	63.00 % 26.50 % 10.50 %	None detected Gray Fibrous Debris

RJ Lee Group, Inc.
 350 Hoxberg Road
 Monroeville, PA 15146

Page 2 of 2