

Ambient Group, Inc.
55 West 39th St., 12th Fl.
New York, New York 10018

Client: SL Green Realty
17 Battery Place
New York, New York

Project ID # 211502
Project Address: 17 Battery Place
Survey Date: 10/13/01

Floor/Location	Concentrations Reported in ug/m ³							
	Cadmium	Chromium	Copper	Iron	Lead	Manganese	Nickel	Zinc
B-N Side Room B21	<0.33	<0.67	47.77	27.57	6.25	3.91	0.56	7.25
2nd Floor/Job Development	<0.5	1.33	<3.83	<33.83	<3.83	<1.17	<0.83	<4.00
3rd Floor/Wildcat Service Corp.	<0.27	<0.54	<2.05	<18.13	<2.05	<0.83	<0.45	<2.14
10th Floor/Reception Area	<0.28	0.65	3.92	<18.94	<2.15	<0.65	<0.47	3.08
12th Floor/In Cubicle D3	<0.26	0.70	<2.02	<17.87	<2.02	<0.62	<0.44	<2.11
14th Floor/Reception Adjacent to Time Clock	<0.03	<0.05	<0.20	<1.80	<0.20	<0.06	<0.04	<0.21
15th Floor/Adjacent ACS Mentoring Program	<0.02	<0.04	<0.16	1.45	<0.16	<0.05	<0.04	<0.17
16th Floor/Adjacent Room 16-D2	<0.02	<0.05	<0.18	<1.57	<0.18	<0.05	<0.04	<0.19
17th Floor/North Side	<0.02	0.07	<0.18	<1.57	<0.18	<0.05	<0.04	<0.19
18th Floor/North Side Empty Office	<0.02	0.05	<0.18	<1.63	<0.18	<0.06	<0.04	<0.19
19th Floor/North Tower, East Face	<0.02	0.07	4.65	<1.47	0.20	<0.05	<0.04	0.66
20th Floor/North Tower, East	<0.03	0.05	<0.02	<1.80	<0.20	<0.06	<0.04	0.23
21st Floor/North Tower, West Face	<0.03	<0.06	<0.21	<1.87	<0.21	<0.08	<0.05	<0.22
22nd Floor	<0.03	<0.05	<0.21	<1.83	<0.21	<0.06	<0.04	<0.22

All levels reported are below their associated standards and guidelines.

Standard/Guideline

OSHA PEL for Cadmium: 5ug/m³

OSHA PEL for Chromium: 1000ug/m³

OSHA PEL for Copper: 1000ug/m³

OSHA PEL for Iron: 10000ug/m³

OSHA PEL for Lead: 50ug/m³

OSHA PEL for Manganese: 1000ug/m³

OSHA PEL for Nickel: 1000ug/m³

OSHA PEL for Zinc: 5000ug/m³

P. 11

FAX NO.

NOV-20-01 TUE 01:14 PM

CITY_21MC100_002836288