NYC 9/11 Public Portal Document

Table 1b
HVAC - Surface Dust
Asbestos Microvac (ASTM 5575)
Return Ducts
New York City Law Department
100 Church Street
New York

* Sample ID :	MV0603	MV0501	MV0401	MV0302	MV0202	MV21RAHF12	MV21RAHF09	MV21RAHF20	MV21RAHF21
Lab Sample ID :	3	5	7	11	14	3	8	10	14
Sample Date :	1/18/02	1/18/02	1/18/02	1/18/02	1/18/02	1/21/02	1/21/02	1/21/02	1/21/02
* Sample Type :	Microvac	Microvac	Microvac	Microvac	Microvac	Microvac	Microvac	Microvac	Microvac
Floor	6	5	4	3	2	21	21	7	7
Location:	Southwest return duct	Southeast return duct	Southeast return duct	Southwest return duct	Southwest return duct	Return air F12 duct	Return air F9 duct	Return air F20 duct	Return air F21 duct
CONSTITUENTS									
ASBESTOS (structures/cm²)	<535	<713	535	<535	**21,400**	**102,006**	<535	6,955	535

* Post Cleaning Target = <10,000 str/cm2 (structures per square centimeter).
< = less than

CITY_21MC100_00651877 6

TRC

NYC-WTC_000220002