



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

ANALYSIS REPORT

ASBESTOS IN AIR

Transmission Electron Microscopy

CLIENT: Department of Design and Construction - 30-30 Thomson Avenue, Long Island City, NY 11101

PROJECT ADDRESS: Stuyvesant H.S., 345 Chambers St., NY, NY 10282 Pier #25

Lab ID#	Client Sample ID#	Sample Location	Volume (liters)	Grid Openings Examined	Filter Area (mm ²)	Analytical Sensitivity (struct/cc air)	Asbestos Type(s)	Asbestos Structures (microns)		Detected Total	Structure Density (struct/mm ²) Total	Structure Concentration (struct/cc) Total
								0.5-5.0	>5.0			
T020414D-01	1	North Entrance of School - East	1803	5	385	0.0043	ND	0	0	0	<20.00	<0.0043
T020414D-02	2	North Entrance of School - West	1800	5	385	0.0043	ND	0	0	0	<20.00	<0.0043

Area Analyzed: 0.0500 mm²

Grid Opening Area: 0.010 mm²

Date Collected: 04/13/02(7:00-17:00)

Analyst: _____

Alex Barengolts

Date Received: 04/14/02

Date Analyzed: 04/14/02

Date of Report: 04/17/02

Lab Manager: _____

David Chen

Analysis performed according to AHERA Method (EPA 40 CFR Part 763 - Appendix A). Samples will be stored for ninety (90) days and then returned to the client upon request.
Sample volume is below recommended limit of the method

AIHA #: 100269

NIST-NVLAP #: 102047

NYS-DOH ELAP#: 11273