NYC 9/11 Public Portal Document

KAM
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTC FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 4-21-02
ADDRESS: 345 Chambers St., NY, NY 10282

TO20421C

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
	PIER 25									
1	North Entrance of school - East	7:01	17:01	3	3	1800	0	0	<20.0	<0.0043
2	-11- — -11- — West	7:02	17:02	3	3	1800	0	0	<20.0	<0.0043

RECEIVED
KAM CONSULTANTS
2002 APR 24 PM 6:43

TECHNICIAN: Renata Dymkowska ROTAMETER KAM101

CHAIN OF CUSTODY	FAX results to DDC.	RECEIVED AT LAB BY: MS SAMPLE CONDITION UPON RECEIPT: Good DATE/TIME:

ANALYST: ALEKS BORGONOVA DATE RECEVED: 4-22-02 DATE OF ANALYSIS 4-22-02

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method
FAX RSULTS TO (212) 941-5356

CITY_21MC100_002911818

NYC-WTC_000220120