

CENTRAL ENVIRONMENTAL INC.

91 McClellan Street, Bronx, NY 10452
 Tel: (718) 293-8727; Fax: (718) 992-4300

AIR MONITORING DATA / CHAIN OF CUSTODY FORM

CLIENT SCHLANG BROS & CO, INC. PHASE: AIR QUALITY TEST (AMBIENT) DATE: 10/16/2001

PROJECT ADDRESS: 99 WALL STREET, NEW YORK, NY PROJECT LOCATION: 27TH FLOOR (ELEVATOR MOTOR ROOM)

TECHNICIAN: AUGUSTINE UWAGBOE JOB #: 01 / 94

Samp. #	Sample Location		Flow In	Flow Out	Time On	Time Off	Total	Total vol.	Fiber Count	Fiber/cc
01	IWA	NORTH SIDE OF ELEVATOR MOTOR ROOM	15	15	1855	2025	90	1350	7	<.002
02	IWA	MIDDLE OF ELEVATOR MOTOR ROOM (27 TH FLR.)	15	15	1857	2026	90	1350	5	<.001
03	IWA	SOUTH WALL OF ELEVATOR MOTOR ROOM (27 TH FL.)	15	15	1857	2027	90	1350	5	<.001
004		F.B.	-	-	-	-	-	-	0	0.000

ANALYZED BY:	DATE	TIME
	10/26/01	
APPROVED BY:		

CITY_21MC100_002388406