NYC 9/11 Public Portal Document

AMBIENT GROUP, INC.
10 MORRIS AVENUE
GLEN COVE, NY 11542

DUST CHARACTERIZATION LABORATORY DATA REPORT

PROJECT ID: 211542
CLIENT: JACK RESNICK & SONS
LOCATION: 75 PARK PLACE
TECHNICIAN: PETER SCHORK

DATE COLLECTED: 11/8/01
DATE RECEIVED: 11/9/01
DATE ANALYZED: 11/13/01

FIELD ID / LABORATORY ID	DESCRIPTION	SAMPLE CONSTITUENTS	PERCENT OF SAMPLE **
211542-07 / DB4078	11TH FLOOR - MIDDLE OF NORTH WALL WINDOW SILL	CELLULOSE	20.0%
		FIBER GLASS	30.0%
		CEMENT DUST	10.0%
		GRAVEL ROAD DUST	30.0%
		CARBON PARTICLES	10.0%
		TOTAL	100.0%

Signed for Ambient Group Inc.

Tarek Fata

TAREK FATA

ND = None Detected, NA = Not Analyzed, There are two (2) types of dust sample submitted for analysis: Settled = Samples submitted on tape/bulk, Airborne = Samples submitted in Air-O-Cell Cassettes. All results disclosed in this report relate only to the items tested. No reproduction of all or any portion of this report shall occur without written approval of Ambient Group Inc. Unless otherwise directed by the Client, Ambient Group Inc. will retain the samples listed in this report for five (5) days, after which time they may be disposed of in accordance with applicable regulations.

CITY_DEP_WORBY_CANNATA_SUBP_000004402

NYC-WTC_000220435