

Ambient Group, Inc.  
10 Morris Avenue  
Glen Cove, NY 11542  
(516) 609-0009

ELAP 10665

**AIRBORNE ASBESTOS STRUCTURES RESULTS  
(TRANSMISSION ELECTRON MICROSCOPY - TEM)**

**Client:** Jack Resnick & Sons, Inc.

**Address:** 75 Park Place

**Project ID:** 211658

| Field ID Number | Date     | Time     | Floor/Sample Location Description                   | Analytical Sensitivity | Asbestos Structures/c |
|-----------------|----------|----------|-----------------------------------------------------|------------------------|-----------------------|
| 1056-01         | 12/20/01 | 10:12 AM | Loading Dock Adjacent to Booth                      | LT ANYL SENS           | < 0.0045              |
| 1056-02         | 12/20/01 | 10:15 AM | Loading Dock at Entrance to Street                  | LT ANYL SENS           | < 0.0045              |
| 1056-03         | 12/20/01 | 10:28 AM | Parking Garage Near Back Exit Upper Level           | LT ANYL SENS           | < 0.0045              |
| 1056-04         | 12/20/01 | 10:30 AM | Parking Garage Adjacent to Soda Machine Upper Level | LT ANYL SENS           | < 0.0045              |
| 1056-05         | 12/20/01 | 10:35 AM | Parking Garage Southend Lower Level                 | LT ANYL SENS           | < 0.0045              |
| 1057-06         | 12/20/01 | 10:37 AM | Parking Garage Northend Lower Level                 | LT ANYL SENS           | < 0.0045              |

LT ANYL SENS = LESS THAN THE ANALYTICAL SENSITIVITY