

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 1 of 6

Time: 7:00 AM LOCATION: PS 234 DATE: 6/6/02 PROJECT NO: 19125-0279

Location	Occupants	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m³)	TVOCs (ppm)
CUTS 112C							
MAIN ENTRANCE	0	74.2	68.1	558	2	112	0
NEXT TO MAIN DESK	0	74.2	68.1	529	2	110	0
NORTHWEST CORNER	0	74.2	68.1	533	2	111	0
WESTSIDE	0	74.5	68.1	515	2	112	0
SOUTHWEST CORNER	0	74.5	68.0	517	2	112	0
COURTYARD	0	74.5	68.1	522	2	111	0
NORTHEAST CORNER	0	74.5	68.1	561	2	109	0
MAIN ENTRANCE	0	74.5	68.1	563	2	109	0
SOUTHEAST CORNER	0	74.5	68.1	544	2	108	0
SOUTHSIDE	0	74.5	68.2	539	2	110	0
Guideline levels ASHRAE/AIHA		68 – 75°F/winter 73-79 °F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m³	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: _____ Date: 6/6/02

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 2 of 6

Time: 11:15 AM LOCATION: PS 234 DATE: 6/6/02 PROJECT NO: 19125-0279

Location	Occupants	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m³)	TVOCs (ppm)
CLASSROOM	25	73.1	52.3	1159	2	28	0
HALL By Gym	0	75.6	56.0	689	2	21	0
Gym	6	75.6	54.7	1055	2	18	0
MAIN FOYER	1	75.8	51.6	641	2	28	0
MAIN LCK	1	75.8	52.3	710	2	26	0
HALL By elevator	1	75.6	52.4	689	2	19	0
HALL By EXIT 1	0	75.7	52.1	599	2	19	0
HALLWAY 114 NEXT TO ROLL	0	75.6	54.1	677	2	22	0
116	15	74.6	53.4	1065	2	18	0
118	0	73.6	52.7	828	2	16	0
Guideline levels ASHRAE/AIHA		68 - 75°F/winter 73-79 °F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m³	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: [Signature]

Date: 6/6/02

CITY_21MCI00_002920687

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 3 of 6

Time: 11:30 AM LOCATION: PS 234 DATE: 6/6/02 PROJECT NO: 19125-0279

Location	Occupants	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m³)	TVOCs (ppm)
323	8	73.5	54.8	810	1	15	0
325	0	74.2	54.8	982	1	16	0
310	0	73.3	54.8	586	1	11	0
324	0	73.2	54.6	601	1	12	0
312 hallway	0	74.9	61.1	587	1	14	0
316	0	73.3	54.2	729	1	16	0
318	1	72.8	53.8	715	1	16	0
320	1	72.4	53.8	652	1	10	0
322	1	72.8	56.0	672	1	12	0
NEXT TO STAIRS - H3 HALLWAY	1	74.3	54.2	851	1	18	0
Guideline levels ASHRAE/AIHA		68 - 75°F/winter 73-79 °F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m³	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: [Signature] Date: 6/6/02

CITY_21MCI00_002920688

**ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT**

Page 4 of 6

Time: 11:40 AM

LOCATION:

PS 234

DATE: 6/6/02 PROJECT NO: 19125-0279

Location	Occupants	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
Hallway next to PM 210	0	73.5	55.0	601	+	16	0
225	0	73.6	54.9	610	2	16	0
223	25	73.6	54.7	1168	2	16	0
Next to elevator bank 2nd floor	0	73.5	55.0	626	2	11	0
214	0	73.6	54.5	710	2	15	0
206	12	72.5	53.7	930	2	18	0
206 Hallway	0	73.6	55.1	591	2	16	0
215	0	73.3	56.1	1011	2	18	0
211	25	73.4	54.5	1140	2	12	0
201	20	74.6	56.2	1126	2	12	0
Guideline levels ASHRAE/AIHA		68 - 75°F/winter 73-79 °F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: [Signature]

Date: 6/6/02

ATC ASSOCIATES, INC. INDOOR AIR QUALITY FIELD REPORT

Page 5 of 6

Time: 12:01 pm LOCATION: PS 234 DATE: 6/6/02 PROJECT NO: 19125-0279

Location	Occupants	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m³)	TVOCs (ppm)
2C2	1	74.9	56.7	581	2	17	0
3C1	2	75.0	57.9	601	2	13	0
H-111(W-1)/3C2	0	75.1	57.9	710	2	18	0
3C5	0	75.3	58.2	717	2	12	0
3C4	0	73.8	56.7	606	2	15	0
311	0	72.7	55.0	586	2	15	0
3C6	3	73.1	54.9	747	2	10	0
315	3	73.7	54.8	626	2	9	0
3C8	0	73.1	52.1	581	2	8	0
319	0	72.6	55.3	714	2	12	0
Guideline levels ASHRAE/AIHA		68 – 75°F/winter 73-79 °F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m³	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: [Signature] Date: 6/6/02

ATC ASSOCIATES, INC. INDOOR AIR QUALITY FIELD REPORT

Page 6 of 6

Time: 12⁴⁶pm LOCATION: PS 234 DATE: 6/6/02 PROJECT NO: 19125-0279

Location	Occupants	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m³)	TVOCs (ppm)
HALLWAY NEXT TO STAIRWELL 3	0	74.1	56.6	629	2	12	0
120	25	73.2	52.7	1262	2	16	0
122	22	74.3	61.0	1145	2	18	0
222	6	74.2	57.2	610	2	11	0
220	4	74.2	57.2	891	2	10	0
HALLWAY 218	0	74.3	57.9	623	2	13	0
216	0	73.3	55.6	641	2	21	0
212	0	73.1	54.1	561	2	16	0
229	25	73.5	54.4	1032	2	19	0
227 Hallway	0	74.5	56.5	701	2	18	0
Guideline levels ASHRAE/AIHA		68 – 75°F/winter 73-79 °F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m³	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: [Signature] Date: 6/6/02